CAN_MOTOR_BOARD V4
10/4/2021



Ord. of soldering:
L1
USBC
STM32
X1
Top ICs
Top R&C
Bottom ICs
Bottom R&C
SS24 after pwr ok
& no short circuit
ECAP
Connectors
D7 if pwr from USB needed