







NOTE: I don't think the Arduino can power everything through it's RAW pin so plug in an external 5V instead and put a diode in line with supply to the Arduino so that it doesn't feed back power to everything else and blow its fuse









