

The condensate sensors at the take off for the first chilled beam served or adjacent to the take off if space is not permitted. Expose the CHW pipe insulation for 100mm and strap the sensor. To be installed as per the condensate sensor manufacturers

> LEVEL 9 CONDENSATE SENSOR MARKUP **AGC-8532-SK-LEVEL 9 CONDENSATE SENSOR**

> > **MARKUP-161101** Rev 1 - NM - 05/10/2016 Rev 2 - NM - 20/10/2016 Rev 3 - NM - 27/10/2016

> > > Rev 4 -NM