



QRev Change Log

Changes 4.33 to 4.34

1. Fixed RS5 frequency display.
2. Fixed reading of SonTek files with long directories.
3. Fix MB correction application.
4. Fix crash resulting from very slow boat movement due to repeated shiptrack coordinates.

Changes 4.32 to 4.33

1. Fixed auto application of MBT correction when no bed is detected.
2. Fix crash resulting from RS5 .mat files containing ping types labeled as 'Other' or '1'

Changes 4.31 to 4.32

1. Fix plotting of error and vertical velocity time series data on WT tab.
2. Add reading of ping types for BT data from RS5, available in the matlab export of RSQ_V2.1.11 or later.
3. Fix reading of firmware version for RS5.

Changes 4.30 to 4.31

1. Fix plotting of error and vertical velocity time series data on the BT tab.

Changes 4.29 to 4.30

1. Upgraded Python to 3.8
2. Fixed crash on main tab due to lollipop plot if oursin not used.
3. Fix crash when changing WT plot options on file loaded from RS5 Qrev matfile due to spaces in ping types when reloading.
4. Fix crash when plotting shiptrack on MvBedTst tab when viewing some older Qrev files.
5. Added config file.
6. Added creation of config file if one does not exist.
7. Modified XML output. The Uncertainty node now contains only the total uncertainty and the model used. Separate nodes are provided for QRev_UA and Oursin details.
8. Fixed issue with salinity entered in WR2 not being applied in QRev
9. Added support for RSL manual speed of sound, temperature, and salinity settings
10. Fixed bug adjusting RSL data to raw values when manual speed of sound, temperature, and salinity settings were applied in RSL
11. Speed of sound correction now applied to vertical boat and water velocities.
12. Fixed bug in Oursin uncertainty model when using GPS reference
13. Fixed bug in GPS tab when all transects do not have GPS data
14. Fixed bug causing Main tab not to update following user input in Oursin uncertainty
15. Fixed bug loading QRev.mat as View then changing to Oursin uncertainty

16. Fixed bug on boat speed plot preventing invalid original data from plotting
17. Fixed bug causing crash if total discharge equals zero
18. Fixed bug for SonTek ADCPs showing no in the xml file CompassCalibrationResult when there is a calibration
19. Fixed bug in manual 3-beam filter setting for water track
20. Fixed bug loading RS5 Matlab data with blank Operator and/or Measurement Number
21. Fixed bug in some dialogs if an edit box is left blank and OK is pressed
22. Fixed bug associated with loading, reprocessing, saving, and then reloading of older *_QRev.mat files
23. Fixed bug causing crash when viewing SNR plot if transect had missing samples
24. Fixed crash when opening a SonTek Matlab file that had no sample data
25. Added scrollbar option to Options dialog for computers with scaling > 125%
26. Added Default X-Axis setting to Options dialog.
27. Added persons, measurement number, and stage start, end, and measurement to xml file.

Changes 4.28 to 4.29

1. Fix crash associated with auto beam filters for TRDI data.

Changes 4.27 to 4.28

1. Fixed crash when opening an older QRev.mat file for a Sontek M9 that had some of the Loop test data marked as edge data.
2. Fixed crash when changing thresholds on older QRev.mat file where bad MBT data was present.
3. Fixed crash associated with plot controls.
4. Fixed crash associated unchecking all options on the compass tab.

Changes 4.26 to 4.27

1. Changed composite depths to interpolate for invalid depths using the composite data rather than the primary reference.
2. WT error and vertical velocity filters are now applied based on ping type for all new processing of data. Loading older QRev files without reprocessing will display previous results.
3. BT error and vertical velocity filters are now applied based on bottom track ping frequency for all new processing of data. Loading older QRev files without reprocessing will display previous results.
4. An option for the jet color map has been added to the Options dialog.
5. Added points to plots in Depth tab
6. Fixed several bugs related to reading RS5 and older QRev files.
7. Added advanced graph tab.
8. Added keyboard shortcuts
9. Added ability to switch x-axis to time or length for time series and contour plots.
10. Added option to export mean cross-section bathymetry within the XML.
11. Fixed crash from nan values present in the Transect data.
12. Fixed crash resulting from import of mmt file with no configuration commands (streampro palm pilot).
13. Added filters for moving-bed tests

14. Added Uncertainty option to the Options dialog.
15. Changed the options for loading existing *_QRev.mat files. The options now are View or Reprocess.
16. Fixed crash when changing the magnetic variation after loading a previously saved QRev file.
17. Added group number to default file name for split initiation save.

Changes 4.25 to 4.26

1. Fix crash resulting from NaN values in BT data for GPS class.
2. Fix crash resulting from loading old QRev files missing setting dict in mat file.
3. Fix crash resulting from missing elements from sticky settings.

Changes 4.24 to 4.25

1. Fixed bug in EDI associated with GPS data.
2. Technical manual update to include explanation of computing discharge in shallow water and corrected table 10.
3. Fixed bug in applying weighted medians when switching from automatic to manual data type
4. Modified extrap subsection so that subsectioning always works from left to right
5. Removed depth from Oursin measured discharge uncertainty
6. Added start date and delta Q to summary table
7. Extrap subsection label changes based on data loaded and processed.
8. Fixed some compatibility issues with RS5 data.
9. Fixed crash associated with Windows OS versions newer than 1909.
10. Fix time formatting on Discharge TS plot so times do not overlap.
11. Fix bug with loading data collected with a PDA and streampro.

Changes 4.23 to 4.24

1. Added user option to prompt for rating on save
2. Added user option to compute extrapolation fit using discharge weighted medians
3. Total measurement discharge will ignore any transect with a discharge that could not be computed
4. Fixed bug reading some old QRev.mat files associated with new rating feature

Changes 4.21 to 4.23

1. New TRDI raw data reader that is 3+ times faster
2. Fixed issue with depth reference drop down menu when depth sounder data were collected
3. Fixed issue so that GPS references that aren't available cannot be selected
4. Fixed several issues with new GPS-BT tab and GPS usage for moving-bed test
5. Fixed bugs in heading interpolation
6. Fixed bug reading *_QRev.mat having only 1 transect
7. Fixed bug when loading measurement with no transects selected
8. Fixed issue that could occur when processing moving-bed tests loaded from *_QRev.mat

Changes 4.16 to 4.21

1. Added code to identify and notify of user changes to original values

2. Added ability to use GPS as a reference for moving-bed tests
3. Applying magvar or heading offset or heading source changes to all transects applies them to moving-bed test also
4. Moving-bed test flow speed now corrected for moving-bed velocity
5. Added automatic checking of GPS lag
6. Added GPS – BT comparison tab to GPS Tab
7. Fixed issue with applying the correct moving-bed test when multiple tests are available
8. Modifications to allow QRev to work with Rowe and Nortek ADCPs.
9. Added support for user edge discharge for WinRiver II 2.22
10. “.mat” is always appended as suffix to saved QRev file
11. Manual threshold for wt and bt saved and displayed when opening *_QRev.mat
12. Modified code to use 1st checked transect rather than 1st transect for general settings
13. Modified code to accept measurements with inconsistent availability of GPS data types
14. Fixed issue loading data with no valid bottom track
15. Added notification when SonTek data is loaded with other than Earth coordinates
16. Fixed issue with selecting transects in EDI if some transects were not checked
17. Fixed issue in EDI if no GPS data are available
18. Fixed QA check for missing samples
19. Fixed issue with invalid stationary moving-bed tests used for correction

Changes 4.15 to 4.16

1. Fixed incomplete system test for TRDI causing crash when saving
2. Fixed issue with PT3 test status not displayed properly
3. Fixed issue with VTG low speed message
4. Fixed issue with VTG and composite tracks on causing switch to GGA
5. Fixed issues with the edges tab: no valid GPS, 0 or 1 ensembles selected, etc.
6. Fixed issues with tab text color not updating properly
7. Updated user’s manual to indicate that 4-beam composite is the default if vertical beam or depth sounder data are available.
8. Several issues with the interaction with RIVRS were fixed
9. Fixed inconsistent behavior of the up/down arrows
10. Improved speed of transect change using up/down arrows
11. Fixed issue with files saving in previously used folder
12. Modified code for compatibility with Nortek Signature 1000

Changes 4.14 to 4.15

1. Fixed issue with shiptrack when all GPS data are invalid
2. Fixed bug when applying stationary moving-bed correction

Changes 4.13 to 4.14

1. Fixed issue with applying a loop test when preceded by a stationary test.
2. Fixed issue with current settings when measurement has mixture of GPS and no GPS

Changes 3.43 to 4.13

1. Ported code from Matlab to Python
2. User interface redesigned using PyQt
3. Main summary page includes contour, shiptrack, and discharge time series graphics
4. Ability to change navigation reference through the toolbar
5. Ability to turn on or off composite tracks through the toolbar
6. Changes to default settings are highlighted
7. Opening and measurement loading speed has been improved
8. Change water velocity interpolation from linear to ABBA
9. Water velocities for all invalid bins are interpolated rather than added to top or bottom extrapolation
10. Fixed bug in vtg primary composite tracks, wasn't substituting GGA
11. Added uncertainty to the automatic comment when a file is saved
12. Statistics and interpolation methods in Python may result in small differences from Matlab

Changes 3.42 to 3.43

1. Fixed bug that did not properly identify missing (lost) ensembles if the typical ensemble duration was greater than 1.5 sec. This affected mode 13 StreamPro data.

Changes 3.41 to 3.42

1. Fixed bug in bottom discharge extrapolation. Previous versions failed to estimate the bottom discharge for ensembles that had no valid data but where depth cell velocities were interpolated.

Changes 3.40 to 3.41

1. Fixed bug with discharge percent change not updating after multiple speed of sound changes.
2. Fixed bug in edges table where wrong row was highlighted if some transects were unchecked.
3. Fixed bug in edges shiptrack so it only displays valid original data and not interpolated data.
4. Fixed bug no allowing manual entry of 0 salinity.

Changes from 3.35 to 3.40

1. Fixed bug causing crash when TRDI PT3 test was incomplete.
2. Modified uncertainty estimate for invalid and edges to use absolute values.
3. Fixed issue with multi-line comments in XML file.
4. Fixed draft check to only evaluate checked transects.
5. XML file now only contains the summary information from a SonTek compass calibration.
6. Fixed bug in moving-bed test if loop compass error and direction could not be computed.
7. Added message for missing samples in SonTek data.
8. Modified PT3 tests to reduce false positives.
9. Added check to boat and wt to check warn if all data are invalid.
10. Edge sign check changed to only show message if edge discharge is greater than 0.5%
11. Added option to store a style sheet with the xml output file.
12. Added _ separator between date and time in default filename.

13. Default compass data view changed to evaluation if evaluation is available.
14. Added upper limit of 45 ppt to salinity input dialog.
15. Added Power/Power default exponent to XML output to support NVE request.
16. Update help file.

Changes to QRev from 3.34 to 3.35

1. Fixed bug causing crash when ADCP had no compass.

Changes to QRev from 3.33 to 3.34

1. Fixed bug causing 25 cm excluded distance to be applied to RiverPro data.

Changes to QRev from 3.31 to 3.33

1. Fixed bug using uncheck all.
2. Fixed bug manually loading system test or compass calibration or evaluation
3. Changed legend location to best
4. Fixed bugs in GUI causing wrong transects to be highlighted
5. Fixed bug reprocessing QRev files associated with moving-bed tests
6. Fixed bug causing changes in draft hOffset, hSource, and magVar to not update QA properly

Changes to QRev from 3.30 to 3.31

1. Fixed bug creating structure for test results from existing QRev files
2. Fixed bug setting status of system test results and button color
3. Fixed bug causing end edge discharge to be applied at start edge
4. Fixed bug preventing user uncertainty from being recomputed after changing a filter or extrapolation
5. Fixed bug displaying number of ensembles to use for edge
6. Changed the algorithm for determining PT3 failure
7. Modified the computation for extrapolation uncertainty to prevent a manual setting from biasing the uncertainty low
8. Added reprocessing of moving-bed tests to reprocessing of existing QRev data files.
9. The mag field, if available, is automatically displayed in the heading graph
10. Modified the excluded distance filter to round to 2 digits to prevent differences when converting between units.

Changes to QRev from 3.28 to 3.30

1. Fixed bugs in messages table that were opening wrong windows.
2. Modified code to interpolate invalid data from composite tracks using the composite tracks rather than the primary data.
3. Modified code to interpolate invalid data from composite depths using the composite depths rather than the primary data.
4. Modified draft check to use display units and limit the comparison to 2 decimal spots which is what is displayed in the GUI.
5. Added code to interpolate discharge for ensembles that are too shallow for a valid depth cell.

6. Modified code in the way that TRDI mmt file setting for composite depths are processed to QRev settings.
7. Moved composite depth computation to end of data input flow.
8. Modified code to allow the view comments button to be accessible even when another window is open.
9. Fixed bug with computePerDiff in extrapolation sensitivity when no transect data provided.
10. Added valid depth method to xml output.
11. Added code to check compass cal errors against USGS recommendations
12. Added code to handle files processed with QBatch.
13. Fixed bug with variable names for mean and max depth and max water speed.
14. Fixed bug with order of warnings and cautions for system test checks.

Changes to QRev from 3.24 to 3.28

1. Messages are now in a table, sorted with warnings on top, and identified with a symbol and font.
2. Clicking on a message will open the associated window, same as clicking on associated button.
3. Extrapolation discharge sensitivity table is now referenced to the currently selected fit, rather than to power/power 0.1667.
4. Clicking a row in the extrapolation discharge sensitivity table will set the fit to those parameters.
5. The compass error from the evaluation of a TRDI ADCP and if available, from RiverSurveyor G3 compass is now shown in the Compass/P/R window.
6. The system test window now displays the total number of tests.
7. The PT3 test is now decoded and the correlation in lag 3 is checked to ensure that the correlation is less than 15% of the lag 0 correlation.
8. A minimum threshold for the boat track vertical velocity filter is set to 0.01 m/s.
9. A bug which applied both the magvar and heading offset to all compass data when loading has been fixed. Now the magvar is only applied to the internal compass and the heading offset only applied to the external compass. This is consistent with how it was handled in the Compass/P/R window.
10. Label for Google Earth plots was changed to filename only, not including the path.
11. Fixed other minor bugs.

Changes to QRev since from 3.23 to 3.24

1. Fixed compiler issue causing the plot to Google Earth to fail
2. Fixed a bug reading longitude data when preceded by a leading zero.

Changes to QRev since release of version 3.21 (in chronological order)

1. Improved the handling of illegal xml characters in mmt file.
2. Added a minimum threshold to the COV QA check for stationary tests.
3. Changed the QA check for number of valid ensembles to a duration based check for stationary moving-bed test.

4. Fixed bug causing edges GUI not to update with changes to table.
5. Added a button to copy comments from the view comments window so they could be pasted in another application.
6. Changed Display Units buttons to Options and created an Options window for units and save all or save checked only.
7. Added an icon button to main window for uncheck all.
8. Change version to 3.22.
9. Fixed bug in when selecting an extrapolation fit where numerical storage prevented $0.1 = 0.1$
10. Fixed issue with RSL revision numbers which need to be 2 digits (02 not 2).
11. Fixed issue with UTC time from GGA which contained an invalid character causing the str2double function resulting in NaN.
12. Added fix for invalid prefPath from corrupt AppData/Local/QRev
13. Added code to reset the close option from extrap to the main window when extrap is closed.
14. Added code to compute the edge velocity using the full profile assuming a 1/6th power fit to estimate the unmeasured portions of the profile.
15. Fixed bug associated with changing all moving-bed tests to manual.
16. Added new message when moving-bed tests are selected manually.
17. Fixed issue with moving-bed tests when data were collected in language other than English.
18. Change version to 3.23

Changes in QRev from 3.12 to 3.21

1. Update help to add pdf file which can be searched.
2. Fixed bug when plotting multiple transects with magnetic data in the Compass/P/R window.
3. Fixed bug with transect name display when some transects were not checked in GPS window.
4. Fixed bug causing Use in main table to be shown in red when there were no errors.
5. Fixed bug checking for invalid edge ensembles due to excluded distance.
6. Fixed bug when using up arrow in Edge window.
7. Fixed bug in xml output for change in speed of sound.
8. Fixed crash when loading transect with only 1 ensemble.
9. Updated use of arrow keys in tables to avoid table and plots getting out of synch when arrow keys were pressed too quickly.
10. Added point marker to vertical beam in depth plots.
11. Modified code to make buttons inactive if no transects are checked.
12. Added EDI interface for Equal Discharge Increment sampling
13. In the extrap window, added message to user that they need to set Fit to manual if they want to use an automatically optimized fit but they have change the threshold, subsection, or data type.

Changes in QRev from version 3.10 to 3.12

1. Fixed bug if number of unchecked transects was greater than number of checked
2. Fixed bug where comments on uncertainty table were not being saved
3. Fixed issue with edge distance check using all transects rather than just checked transects
4. Fixed bug where temperature messages were based on all transects rather than just the checked transects

5. Fixed bug where magError and GPS heading were saved as column vector rather than row vector
6. Fixed bug where max and min pitch and roll limits were not set for G2 compass, now set to nan
7. Improved scaling for magError and pitch and roll, 2) linked x axes of top and bottom plots
8. Added code to add qTotalCaution to older QRev files
9. Fixed bug when there is no pitch and roll data (old SonTek files)
10. Fixed bug when selecting use when moving-bed test is not user valid
11. Fixed bug when loading QRev files from 2.9x by adding code to create the qTotalCaution field
12. Fixed bug when G2 compass was processed with current RSL resulting in Compass pitch and roll limits set to large number
13. Added version numbers to popup when loading older QRev file
14. kml Google earth file now plots the full transect filename
15. Added a minimum threshold to the bottom track error velocity automatic filter
16. Fixed bug interpolating depths for lost ensembles
17. Fixed bug preventing automatic excluded distance for RioPro
18. Fixed bug graphing of invalid data when excluded distance is set
19. Fixed bug plotting data when all data are invalid
20. Fixed bug applying user specified edge Q in RiverSurveyor Live
21. Fixed bug when no station name or number was provided for compatibility with XML standards