Insured/Applicant Name:	Mr. ABC	Appli	cation / Policy #:	6293CGg267				
Address Inspected: 1345	Marseille Dr, Miami Beach FL 33141							
Actual Year Built: 1949		Date Inspected:	12/20/2021					
Minimum Photo Requirements ☑ Dwelling: Each side ☑ Roof: Each slope ☑ Plumbing: Water heater, under cabinet plumbing/drains, exposed valves ☑ Main electrical service panel with interior door label ☑ Electrical box with panel off ☑ All hazards or deficiencies noted in this report								
A Florida-licensed inspector must complete, sign and date this form.								

Be advised that Underwriting will rely on the information in this sample form, or a similar form, that is obtained from the Florida licensed professional of your choice. This information only is used to determine insurability and is not a warranty or assurance of the suitability, fitness or longevity of any of the systems inspected.

Electrical System Separate documentation of any aluminum wiring remediation must be provided and certified by a licensed electrician.							
Main Panel		Second Panel					
Type: ☑ Circuit breaker ☐ Fuse		Type: ☑ Circuit breaker ☐ Fuse					
Total Amps: 125		Total Amps: 125					
Is amperage sufficient for current usage? Yes No	o (explain)	Is amperage sufficient for current usage? Yes \(\subseteq \text{No (explain)} \)					
Indicate presence of any of the following:		I					
☐ Cloth wiring							
Active knob and tube							
☐ Branch circuit aluminum wiring (If present, describe the usage of all aluminum wiring):							
* If single strand (aluminum branch) wiring, provide	details of all remediation. Se	eparate documentation of a	ll work must be provided.				
☐ Connections repair via COPALUM crimp							
Connections repair via AlumniConn							
Hazards Present		D. II.					
		Double taps					
☐ Blowing fuses		☐ Exposed wiring					
☐ Tripping breakers		☐ Unsafe wiring					
☐ Empty sockets		☐ Improper breaker size					
☐ Loose Wiring		☐ Scorching					
☐ Improper grounding		☐ Other (explain)					
☐ Corrosion							
Over fusing							
General condition of the electrical system: ☐ Satisfa	actory V Unsatisfactory(ex	 plain)					
Double tapped breaker was noted in the secondar							
Supplemental information							
Main Panel	Second Panel		Wiring Type ✓ Copper				
Panel age:	Panel age:						
Year last updated:	Year last updated:		✓ NM, BX or Conduit				
Brand/Model: General Electric	Brand/Model: General Electric						

Central AC: ✓ Yes No							
Central heat: ✓ Yes No							
If not central heat, indicate primary heat source and fuel type:							
Are the heating, ventilation and air conditioning systems in good working order? ✓ Yes □ No (explain)							
Date of last HVAC servicing/inspection:							
Hazards Present							
Wood burning stove or central gas fireplace <i>not</i> professionally installed? ☐ Yes ☑No Space heater used as primary heat source? ☐ Yes ☑No							
Is the source portable? ☐ Yes ☑ No							
Does the air handler/condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area?							
☐ Yes ☑No							
Supplemental Information							
Age of system: ⁵							
Year last updated: ²⁰¹⁶ (Please attach photo(s) of HVAC equipment, including dated manufacturer's plate)							
(t rease action photo(s) of 11 v/10 equipment, including dated manufacturer's plate)							
Plumbing System							
Is there a temperature pressure relief valve on the water heater? 🗹 Yes 🗆 No							
Is there any indication of an active leak? ☐ Yes ☑ No							
Is there any indication of a prior leak? Yes No Water heater location: Extension will the allocate							
Water fleater location: Exterior utility closet							
General condition of the following plumbing fixtures and connections to applicances:							
Satisfactory Unsatisfactory N/A Satisfactory Unsatisfactory N/A							
Dishwasher							
Refrigerator Sinks							
Washing Machine Sump pump Sump pump							
Water Heater ✓ ☐ Main shut off valve ✓ ☐ Showers/Tubs ✓ ☐ All other visible ✓ ☐							
If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.).							
Supplemental Information							
A CDimin- Contains							
X O : : 14.1							
Completely re-piped							
Partially re-piped (Provide year and extent of renovation in the comments below)							
(Provide year and extent of renovation in the comments below)							
(Provide year and extent of renovation in the comments below) ☐ PEX ☐ Polybutylene							

Roof (With photos of each roof slope, this section can take the place of the <i>Roof Inspection Form.</i>)						
Predominant Roof Covering material: Modified Bitumen Roof age (years): 25 Remaining useful life (years): 5 Date of last roofing permit: 07/03/1996 Date of last update: 07/03/1996 If updated (check one):		Secondary Roof Covering material: 3-Tab Roof age (years): 25 Remaining useful life (years): 5 Date of last roofing permit: 07/03/1996 Date of last update: If updated (check one):				
☐ Full Replacement ☐ Partial Replacement % of replacement Overall condition:		✓ Full Replacement ☐ Partial Replacement % of replacement Overall condition:				
✓ Satisfactory ☐ Unsatisfactory (explain below)		☑ Satisfactory ☐ Unsatisfactory (explain below)				
Any visible signs of damage / deterioration (check all that apply and explain below) Cracking Cupping/Curling Excessive granule loss Exposed asphalt Exposed felt Missing/loose/cracked tabs or tiles Soft spots in decking Visible hail damage Any visible signs of leaks Yes No Attic/underside of decking Yes No Interior ceilings Yes No	n?	Any visible signs of damage / deterioration (check all that apply and explain below) Cracking Cupping/Curling Excessive granule loss Exposed asphalt Exposed felt Missing/loose/cracked tabs or tiles Soft spots in decking Visible hail damage Any visible signs of leaks Yes Moo Attic/underside of decking Yes No Interior ceilings Yes Moo	on?			
Additional Comments/Observations(use additional pages if needed):						
All 4-Point Inspection Formsmust be completed and signed by a verifiable Florida-licensed inspector. I certify that the above statements are true and correct.						
Joseph Bravo Inspector Signature	InterNachi CPI Title	HI10320 License Number	12/29/2021 Date			
A1 Florida Home Inspections Company Name	Home Inspector License Type	305-898-6123 Work Phone				

Special Instructions: This sample 4-Point Inspection Formincludes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

Photo Requirements

Photos must accompany each 4-Point Inspection Form. The minimum photo requirements include:

- Dwelling: Each side
- Roof: Each slope
- Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- Open main electrical panel and interior door
- Electrical box with the panel off
- · Allhazards or deficiencies

Inspector Requirements

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. Examples include:

- · A general, residential, or building contractor
- · A building code inspector
- · A home inspector

Note: A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

Documenting the Condition of Each System

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

Additional Comments or Observations

This section of the 4-Point Inspection Formmust be completed with full details/descriptions if any of the following are noted on the inspection:

- Updates: Identify the types of updates, dates completed and by whom
- Any visible hazards or deficiencies
- · Any system determined not to be in good working order

Note to All Agents

The writing agent must review each 4-Point Inspection Form before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies.

Photos, Additional Comments or Observations

Exterior Photos




Electrical System


















Double tap the breaker and secondary electric panel

HVAC System

HVAC Equipment









Plumbing System

Water Heater



Under cabinet plumbing & drains





Exposed Valves



RoofPhotos of Each Slope

