

INSPECTION REPORT

IndAI Plant — Quarterly Equipment Inspection

Document No: IR-2024-Q3-009 | Date: 15/09/2024

Equipment: Compressor C-201 | Location: Unit 1 — Gas Compression

Inspection Summary

Quarterly inspection conducted on Compressor C-201 on 15/09/2024 by Inspector Priya Sharma. Compressor C-201 showed signs of overheating in the discharge section. Discharge temperature recorded at 185 degrees C against normal operating limit of 160 degrees C. Valve leak detected on the second stage suction valve. Corrosion observed on the cooler inlet nozzle.

Findings

Parameter	Measured Value	Limit	Status
Discharge Temp	185 C	160 C	FAIL
Suction Pressure	4.2 bar	4.0-4.8 bar	OK
Vibration Level	9.5 mm/s	7.0 mm/s	FAIL
Bearing Temp	78 C	80 C	OK
Lubrication Level	Low	Normal	FAIL

Recommendation: Immediate shutdown for valve replacement and cooler cleaning. Schedule overhaul within 7 days. Next inspection due: 15/12/2024.