

In functional state we need to do following things

1. All the kill signal to the pipeline should be 0
2. csr save cause should be 0, i.e noting needs to be saved
3. pc_valid will be 0, since normal PC needs to there in IF stage

