

INDUSTRIAL BRAIN	Calibration Report	Doc ID: Calibration_Report_HX11
	Effective: 2023-01-01	Rev: 1.0

Instrument Calibration Report

Asset: Heat Exchanger HX-11 (Outlet Temp Transmitter TT-1102) **Date:** 2023-07-05 **Technician:** Maria Gonzalez

Procedure: 5-point calibration check. **Results:** Sensor drift was within acceptable 0.5% tolerance. No adjustments made.

Prepared By / Technician

Approved By / Supervisor