


Motor Control Box Schematic

35 W, 12V
30 RPM
X2



Not to Scale

Sensor Control Box Schematic

