



3.55. Proceed with caution hand signal.—

Indication: Proceed slowly reducing speed further if the signal is given at a progressively slower rate.

How given by day: By waving a green flag vertically up and down or by waving one arm in a similar manner as illustrated below:



How given by night: By waving a green light vertically up and down as illustrated below:



Note: When the speed is to be reduced further, this signal shall be given at a slower and slower rate and when a stop is desired, the Stop hand signal shall be shown.