

GREATEST OF 2 NUMBERS

EXP NO: 8

GNUSim8085 - 8085 Microprocessor Simulator

File Reset Assembler Debug Help

Registers

Register	Value
A	1D
BC	1D 00
DE	00 00
HL	00 00
PSW	00 00
PC	42 10
SP	FF FF
Int-Reg	00

Flag

Flag	Value
S	1
Z	0
AC	0
P	1
C	1

Load me at

```
1 LDA 2050
2 MOV B,A
3 LDA 2051
4 CMP B
5 JNC STORE
6 MOV A,B
7 STORE: STA 2052
8 HLT
```

Memory

Address (Hex)	Address	Data
0802	2050	29
0803	2051	22
0804	2052	29
0805	2053	0
0806	2054	0
0807	2055	0
0808	2056	0
0809	2057	0
080A	2058	0
080B	2059	0
080C	2060	0
080D	2061	0
080E	2062	0
080F	2063	0

Line No Assembler Message

```
0 Program assembled successfully
```

Simulator: Idle

SMALLEST OF 2 NUMBERS

EXP NO: 9

GNUSim8085 - 8085 Microprocessor Simulator

FileResetAssemblerDebugHelp

Registers

A16

BC1D00

DE0000

HL0000

PSW0000

PC4210

SPFFFF

Int-Reg00

Flag

S1

Z0

AC0

P1

C1

Decimal - Hex Conversion

DecimalHex

00

To HexTo Dec

I/O Ports

0-+00

Update Port Value

Memory

2051-+16

Update Memory

Load me at

1LDA 2050

2MOV B,A

3LDA 2051

4CMP B

5JC STORE

6MOV A,B

7STORE: STA 2052

8HLT

DataStackKeyPadMemoryI/O Ports

Start2050OK

Address (Hex)	Address	Data
0802	2050	29
0803	2051	22
0804	2052	22
0805	2053	0
0806	2054	0
0807	2055	0
0808	2056	0
0809	2057	0
080A	2058	0
080B	2059	0
080C	2060	0
080D	2061	0
080E	2062	0
080F	2063	0

Line NoAssembler Message

0Program assembled successfully

Simulator: Idle

1's COMPLIMENT

EXP NO: 11

GNUSim8085 - 8085 Microprocessor Simulator

File Reset Assembler Debug Help

Registers

Register	Value
A	F9
BC	06 04
DE	00 00
HL	00 00
PSW	00 00
PC	42 08
SP	FF FF
Int-Reg	00

Flag

Flag	Value
S	1
Z	0
AC	0
P	1
C	1

Load me at

```
1 LDA 8000
2 CMA
3 STA 8001
4 HLT
```

Decimal - Hex Conversion

Decimal: 0 Hex: 0

To Hex To Dec

I/O Ports

0 - + 00

Update Port Value

Memory

8000 - + 06

Update Memory

Start 8000 OK

Address (Hex)	Address	Data
1F40	8000	6
1F41	8001	249
1F42	8002	0
1F43	8003	0
1F44	8004	0
1F45	8005	0
1F46	8006	0
1F47	8007	0
1F48	8008	0
1F49	8009	0
1F4A	8010	0
1F4B	8011	0
1F4C	8012	0
1F4D	8013	0

Line No Assembler Message

```
0 Program assembled successfully
```

Simulator: Idle

2's COMPLIMENT

EXP NO: 12

GNUSim8085 - 8085 Microprocessor Simulator

File Reset Assembler Debug Help

Registers

Register	Value
A	FA
BC	06 04
DE	00 00
HL	00 00
PSW	00 00
PC	42 09
SP	FF FF
Int-Reg	00

Flag

Flag	Value
S	1
Z	0
AC	0
P	1
C	1

Load me at

```
1 LDA 8000
2 CMA
3 INR A
4 STA 8001
5 HLT
```

Decimal - Hex Conversion

Decimal	Hex
0	0

I/O Ports

Port	Value
0	00

Memory

Address	Value
8000	06

Start 8000 OK

Address (Hex)	Address	Data
1F40	8000	6
1F41	8001	250
1F42	8002	0
1F43	8003	0
1F44	8004	0
1F45	8005	0
1F46	8006	0
1F47	8007	0
1F48	8008	0
1F49	8009	0
1F4A	8010	0
1F4B	8011	0
1F4C	8012	0
1F4D	8013	0

Line No Assembler Message

```
0 Program assembled successfully
```

Simulator: Idle