AXon Manufacturing Analytics — KPI Cheat Sheet (19 KPIs)

by Mahendra Singh · Production & Efficiency + Quality & Rejection Dashboards

PRODUCTION DASHBOARD KPIS

Total Work Orders
`COUNT(DISTINCT Doc_Num) WHERE Doc_Num IS NOT NULL`
The count of distinct, non-blank work order documents (Doc_Num) raised in fact_Production.

Total WO Qty (Ordered)
`SUM(WO_Qty)`
The sum of the quantity originally specified on each work order.

Total Manufactured (Produced) Qty
`SUM(Produced_Qty)`
The total quantity of finished goods produced across all work orders.

Total Processed Qty
`SUM(Processed_Qty)`
The total quantity that completed processing at a given operation/machine, before the final produced-quantity step.

Efficiency Rate %
`SUM(Produced_Qty) / SUM(Processed_Qty) × 100`
How much of what was processed actually became finished, produced output.

Machine Utilization %
`SUM(Processed_Qty) / SUM(WO_Qty) × 100`
Processed quantity as a percentage of the quantity originally ordered.

Total Manufacturing Cost
`SUM(Total_Value)`
The total value of everything produced, in the plant's local currency.

Cost per Unit
`SUM(Total_Value) / SUM(Produced_Qty)`
The average manufacturing cost of one finished unit.

Avg Per-Day Machine Cost
`AVG(Per_Day_Machine_Cost)`
The average daily operating cost per machine across all production records.

On-Time Delivery %
`COUNT(Delivery_Status='On Time') / COUNT(Doc_Num IS NOT NULL) × 100`
The percentage of real work orders delivered exactly on their scheduled date — not early, not late.

Repeat Order %
`COUNT(Is_Repeat_Order='Yes') / COUNT(Doc_Num IS NOT NULL) × 100`
The percentage of real work orders that are repeat orders from an existing buyer relationship, rather than first-time orders.

QUALITY DASHBOARD KPIS

Total Rejected Qty
`SUM(Rejected_Qty)`
The total quantity of units rejected across all production records.

Rejection Rate %
`SUM(Rejected_Qty) / SUM(Produced_Qty) × 100`
Rejected quantity as a percentage of produced quantity.

Wastage %
`SUM(Rejected_Qty) / SUM(Processed_Qty) × 100`
Rejected quantity as a percentage of processed quantity.

Total Wastage %
`SUM(Rejected_Qty) / (SUM(Produced_Qty) - SUM(Rejected_Qty)) × 100`
Rejected quantity as a percentage of net good production (produced quantity minus the rejected quantity itself).

Employee-wise Rejected Qty
`SUM(Rejected_Qty) GROUP BY Employee_Code`
Total rejected quantity attributed to each employee, ranked to surface outliers.

Machine-wise Rejected Qty
`SUM(Rejected_Qty) GROUP BY Machine_Code`
Total rejected quantity attributed to each machine, ranked to identify underperforming equipment.

Operation-wise Rejected Qty
`SUM(Rejected_Qty) GROUP BY Operation_Code`
Total rejected quantity attributed to each manufacturing operation (weaving, cutting, printing, etc.).

Department-wise Manufacture vs Rejected
`SUM(Produced_Qty), SUM(Rejected_Qty) GROUP BY Dept_ID`
Produced quantity and rejected quantity broken down by department, to compare quality performance across production areas.