Main Phases of Screenprint Process

- 1. Selection of inks (inks must be warmed before printed if stored in cold)
- 2. Selection of substrate
- 3. Selection of mesh
- 4. Additional tools needed
- 5. Squeegee selection
- 6. Power up printing machine and selection of printing parameters
- 7. Inspection of a printing mesh
- 8. Attachment of the mesh
- 9. Decision of printing parameters and test print (squeegee up)
- 10. Ink preparation
- 11. Attachment of the substrate
- 12. Printing
- 13. Drying
- 14. Measurements and checking



18 September 2014

Timo Vainio

Main Phases of Inkjet Process

- Selection of inks
- 2. Selection of substrate
- 3. Additional tools needed
- 4. Filling of ink cartridge
- 5. Power up printer
- 6. Setting of printing parameters
- 7. Assembling of cartridge and substrate
- 8. Adjusting of ink droplet
- 9. Printing
- 10. Drying
- 11. Measurements and checking



18 September 2014

Main Phases of Dispensing Process

- 1. Design file preparation
- 2. Selection of inks
- 3. Selection of substrate
- 4. Preparation of dispensing head
- 5. Power up dispenser
- 6. Run dispenser "dry"
- 7. Printing
- 8. Drying
- 9. Measurements and checking



18 September 2014

Main Phases of R2R Process

- 1. Selection of inks
- 2. Selection of substrate
- 3. Additional tools needed
- 4. Installation
- 5. Power up R2R machine
- 6. Run R2R "dry"
- 7. Power up oven
- 8. Printing
- 9. Drying
- 10. Measurements and checking

