

SOP: Pipeline Gasket Maintenance Procedure

Section 1.0: Piping System Repairs

Procedures for minor line replacements and gasket repairs.

Section 2.0: Permitting Requirements

A cold work permit is required for line breaking. However, if the pipeline pressure is confirmed to be below 5 bar, work may proceed without a work permit, provided the line is blocked at upstream valves.