

OISD-STD-105: Work Permit System

Clause 4.1: General Permit Rules

A work permit is a written document authorizing specific work to be carried out in a specific area. No hot work, cold work, or confined space entry shall be performed without a valid permit issued by an authorized receiver and issuer.

Clause 4.2.1: Atmosphere Gas Testing

Gas testing must be performed by a competent person certified by the safety department. Entry shall only be allowed if: Oxygen content is between 19.5% and 23.5% by volume, Flammable gases (LEL) are below 1.0%, and Toxic gas concentrations are below threshold limit values (e.g. H₂S below 10 ppm).

Clause 4.2.2: Permit Shift Validity

A work permit shall be valid for a maximum of one shift or 12 hours, whichever is less. A fresh permit or renewal is required if the work extends beyond the authorized shift. Re-testing of the atmosphere is mandatory upon permit renewal or if work is suspended for more than 2 hours.

Clause 5.1: Isolation and Energy Control

All energy sources (electrical, mechanical, hydraulic) must be isolated, locked out, and tagged out (LOTO) prior to confined space entry. Physical blinding or disconnection of process piping is mandatory to prevent material entry.

Clause 5.2: Rescue and Observer Standby

A standby person must be stationed at the entrance of the confined space at all times. The standby person must remain at the entrance and monitor entrants. Under no circumstances shall the standby person leave the entrance or enter the space. A safety harness and lifeline must be worn by entrants, and rescue equipment must be available on-site.

Clause 6.1: Hot Work Fire Precautions

All combustible materials must be removed or protected within a radius of 15 meters from the hot work location. A designated fire watch with appropriate firefighting equipment (extinguishers, fire hose) must be present.