

This list includes items that should be packed/prepared for use by **all** Burnsview VEX Robotics teams during a competition. Many of the items on this list are extremely vital, so team members should prioritize this list before packing for their individual teams.

1. General			Couplers	
	Arrange transportation to and from		Bearing flats	
	competition for all members		Axle locks (lock plates)	
	Ensure everyone has robotics clothing		Shafts (various sizes)	
			Spacers (all sizes, black and white)	
2. Electronics			Gears (all sizes, normal and high strength)	
	Dremel		Chains	
	Extension cord		Sprockets (all sizes)	
	Power bars (min. 2)		Wheels (normal and omni)	
	V5 Battery chargers (min. 1 per team)			
	V5 Controller chargers (min. 1 per team)	6. Spares (if possible)		
			V5 Batteries	
3. Too	ls		V5 Motors	
	3/32" T-handle Allen keys		V5 Brains	
	5/64" T-handle Allen keys		V5 Smart Cables	
	Robertson screwdrivers			
	Nut drivers/wrenches	7. Mis	7. Miscellaneous	
	Needle-nose pliers		Game objects (eg. balls)	
	Wire cutters		Zip ties	
	Hack saw and vice		Elastics	
	Measuring tape		Electrical tape	
	Hammer		Scissors	
	File		Masking tape	
4. Metal (various sizes)				
	Steel bars (plates)			
	Standoffs			
	C-channels			
	Angles (L-channels)			
	Gussets			
5. Parts				
	Screws (all sizes, silver and black)			
	Nuts (keps and nylocks)			
	Pillow block bearing			
	Shaft collars			