```
#include <P18F4520.h>
void main(void)
{
   TXSTA=0x20; //choose low baud rate, 8-bit
   SPBRG=15; //9600 baud rate/ XTAL 10 MHz
   TXSTAbits.TXEN=1; // Enable transmission
   RCSTAbits.SPEN=1; // Enable serial port (configures TX/CK pins)
   while (1)
   {
    TXREG='G'; //place value in buffer
   while (PIR1bits.TXIF==0); //wait until all gone
}
```