

VEHICLE REPAIR ESTIMATION SLIP

Job Card No.:
JC-UP-2026-0734

Date:
14 June 2026

CUSTOMER & VEHICLE DETAILS

Customer Name:
Meera Iyer

Vehicle:
Maruti Suzuki Baleno Alpha

Registration No.:
UP-27-AS-2525

Odometer Reading:
32,150 km

Insurance / Policy No.:
POL-445566

#	Part / Service Description	Work Type	Qty	Source	Amount (Rs.)
1	Front Bumper (OEM)	Replace + Paint	1	OEM	11,000
2	Bonnet (OEM)	Repair + Paint	1	OEM	18,500
3	Headlight Left Assembly (OEM)	Replace	1	OEM	13,500
4	Headlight Right Assembly (OEM)	Replace	1	OEM	13,500
5	Radiator Grille (OEM)	Replace	1	OEM	4,800
6	Front Left Fender (OEM)	Repair + Paint	1	OEM	12,000
7	Radiator Core Assembly (OEM)	Replace	1	OEM	16,500
8	Labour - Panel Beating & Alignment	Labour	1	-	14,000
9	Labour - Full Front Paint Blend	Labour	1	-	11,000
10	Consumables (Primer, Polish, Masking)	Material	1	-	5,200
Sub-Total					Rs. 120,000
CGST @ 9%					Rs. 10,800
SGST @ 9%					Rs. 10,800
GRAND TOTAL					Rs. 141,600

Note: WARNING (for demo): This estimate is intentionally inflated by approx 80% above fair OEM+labour rates. Non-empanelled workshop. Refer to fraud screening (FC-17 / FS-004).

Sd/- Meera Iyer
Customer Signature
(Meera Iyer)

Sd/- Ganga Motors & Body Works
Authorised Signatory
(Ganga Motors & Body Works)