

Model Information

Model:
RandomForestClassifier

Features: 6

Instructions

1. Enter machine sensor readings
2. Click 'Predict' to analyze
3. Review the prediction results
4. Take appropriate maintenance action



Predictive Maintenance Dashboard



Prediction



Analytics



About

Machine Health Prediction



Machine Sensor Readings

Temperature & Speed



Air temperature [K]



300.00

-

+



Process temperature [K]



300.00

-

+



Rotational speed [rpm]



1500

-

+



Torque [Nm]



40.00

-

+

Tool Wear & Failures



Tool wear [min]



100

-

+



Type



0

▼

Analyze Machine Health



**MACHINE
OPERATING
NORMALLY**


Failure Probability:

42.00%

Continue regular
monitoring

Risk Level: ● LOW RISK

Failure Probability (%)



Detailed Analysis

Failure Probability

42.0%

Normal Probability

58.0%

Prediction Confidence

58.0%