TÜV SÜD MIDDLE EAST LLC
P.O Box: 45117, Abu Dhabi - U.A.E
Tel.: +971 2 6767 600 | Fax: +971 2 6762 224
Email: ad.report@tuvsud.com
Email: info.me@tuvsud.com
Website: www.tuv-sud.ae

تو ف سود ميدل ايست ذ.م.م.
المكتب الرئيسي : ص.ب ٤٥١١٧ أبو ظبي - أ.ع.م.
هاتف: ٩٧١٢٦٧٦٧٦٠٠+ فاكس: ٩٧١٢٦٧٦٢٢٢٤+

Add value.
Inspire trust.

TÜV®

REPORT NO.
AU-HP-26-41060/40845/42-GL

STICKER NO: 42
Timesheet No.: 1113862

REJECTION REPORT OF A WEBBING SLINGS

Time Sheet: AU 1113862 **Reviewer: GL**

Name & Address of the Owner of the Equipment **M//s. Sulzer ASOS L.L.C, Abu Dhabi, U.A.E.**			Date of Examination **21-08-2026**
Description of the Lifting Tackles (type, use, size, capacity, etc) **Flat Polyester Webbing Sling**			
Name & Address of Maker of the Lifting Tackle **N/A**		Year Manufactured **Not seen**	Test Certificate Issued (Yes / No) **NO**
Type/Model No. **N/A**	Serial No. **As Below**	Registration No. **N/A**	Owner's Identification Mark/No. **N/A**
Location of Lifting Tackles: **Kizad, Abu Dhabi U.A.E.**		Relevant standard: **BS EN 1492-1:2000 + A1:2008**	Capacity **3 ton**

Defects Noted and Alteration or Repairs Required before Registration

Serial No	Condition of Component	Recommended Action
107433-3/1 107433-3/2 107433-3/3 107433-3/4 109711-11/1 109711-13/1 (Qty. 6 nos.)	• Cuts in various parts of the Sling has been found. • Abrasion wear in various parts of the Sling has been found. • Chemical attacks have been found.	Remove out from service

------ End of Report ------

Note:
a.) This Webbing Sling is ***unsafe to use***.
b.) This Webbing Sling is ***to be removed from service***.

Unsafe to Use

The report is issued subject to the condition that it is understood and agreed that nothing in this report shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer or operator of any warranty, expressed or implied, and TÜV SÜD Middle East, LLC shall be limited to the acts or omissions of its employees, agents and subcontractors. Under no circumstances whatsoever shall TÜV SÜD Middle East, LLC be liable for any injury or damage to any person, or occurring by reason of negligent operation or any defect in materials, machinery, equipment or other items other than such defects ascertainable by normally accepted testing standards and only those items inspected by TÜV SÜD Middle East, LLC and which are covered by this report.

07-09-2026 10:53:50 - VERIFY CERTIFICATES @ https://verify-tuvsudme.com

As far as may be ascertained for this general examination, without detailed removals or opening up to expose parts ordinarily concealed; and without taking gaugings to ascertain thickness of structural members; or full load and operational testing, this pre-test examination is submitted.
Any of this Report aforementioned defects or repairs required to the Equipment's material or components which may affect its continuous safe working use shall be rectified and subjected to re-inspection prior to full continuous operation and the "Registry of Test and Examination" of this equipment.
This Report should be attached to the Registry when completed and found acceptable. The Equipment's Owner or Operator shall be responsible for operating the equipment, until such rectifications as required, are done satisfactorily.

For and on behalf of TÜV SÜV Middle East

Date: **21-08-2026**

Stamp

Inspected by:_____
Hussain Salih
(Inspection Engineer)

Approved by:_____
Mohammed Fazal
(Operations Manager)

Unsafe to use

LIABILITY - the Client or his assignee or supervisor in interest agrees to indemnify and hold harmless TÜV SÜD Middle East, LLC from and against any and all claims, demands, lawsuits or actions for damages, including legal fees to persons and / or property tangible, intangible or otherwise which may be brought against TÜV SÜD Middle East, LLC incidental to, arising out of or in connection with the work to be done, services to be performed or material to be furnished hereunder except for those claims caused solely and completely by the negligence of TÜV SÜD Middle East, LLC, its directors, officers, employees or sub-contractors.

Under no circumstances whatsoever shall TÜV SÜD Middle East, LLC be liable for any injury or damage to any person or property occurring by reason of any defect in all design, materials, machinery, equipment or other items which it is the responsibility of TÜV SÜD Middle East, LLC to inspect under the terms specified hereunder. Nothing herein contained shall be deemed to relieve any seller or manufacturer of its warranties, express or implied.

In the event TÜV SÜD Middle East, LLC is proven negligent in any respect, the liability of, TÜV SÜD Middle East, LLC its agents, employees and subcontractors for Proprietors claims shall not exceed the greater of US$ 1,000 or five (5) time the total compensation paid to TÜV SÜD Middle East, LLC for the work. Proprietor shall save, defend and hold TÜV SÜD Middle East, LLC harmless against in excess of US$ 1,000 or five (5) times the total compensation paid to TÜV SÜD Middle East, LLC.