

Before you leave the build lab

Holybro X500 V2 · ArduPilot Copter · Mission Planner · indoor, GPS-denied, **Stabilize** mode only

01 Equipment to carry

Count it out loud

- ☐ Aircraft, **propellers removed** — carried by hand, by the **centre plate**, never by an arm
- ☐ 4 propellers per aircraft + one spare set, bagged — **CW and CCW separate**
- ☐ **RC transmitter**, charged to $\geq 50\%$
- ☐ Laptop, **charged**, plus its charger
- ☐ SiK 433 MHz **ground** radio + its USB cable
- ☐ Hex driver set (1.5 / 2.0 / 2.5 / 3.0 mm)

02 Batteries

Each pack

- ☐ Each pack inspected: **no puffing, dents, punctures or smell**, wrap intact
- ☐ Each pack on the checker: $\geq 16.6\text{ V}$ and **cell spread** $\leq 0.05\text{ V}$

03 Physical inspection

Propellers stay off

- ☐ Each of the four arms: **no cracks, no splits, no crushing** at the clamp
- ☐ Arm clamp screws tight — twist each arm by hand, it must not move
- ☐ Spin each motor by hand: **smooth, silent, no grinding, no scraping**
- ☐ Every connector seated: ESC to PDB, PM02 in and out, **GPS1**, **TELEM1**, **GPS2**
- ☐ **No wire anywhere inside the propeller arc.** Trace all four
- ☐ **Shake test.** Hold the frame by the centre plate and shake it firmly. Nothing rattles, nothing swings

04 Calibrations

Propellers off

- ☐ **Accelerometer** — full six-position calibration completed and accepted
- ☐ **Level horizon** — on a surface you have checked is level
- ☐ **Radio** — every stick to both endpoints, every switch seen to register
- ☐ Flight mode switch: **Stabilize** on the position the pilot will use
- ☐ **Motor test in Mission Planner, propellers off** — each motor runs in the position and direction the frame diagram shows