


3679-N6



3679-S10

It should be recognised that cable depths shown on this map may be unreliable as the ground level may have changed since the original survey. Therefore, any excavation should be carried out with the necessary precautions due to the alteration of original landmarks.


3679-S10

LV Operational Map 8
H.V. Cable Map No. 13

The position of apparatus shown on this map is believed to be correct but original landmarks may have altered since the apparatus was installed. The exact position of the apparatus should be verified by the user of a suitable surveying instrument before excavation commences.
For more details please telephone 01 753 5611 Ext. 8236.

London Electricity Board
Based upon the Ordnance Survey Map with the sanction of the Controller of HM Stationery Office (Crown Copyright Reserved)

SCALE 1 = 500



GEORGIN 10071