

## Master Data Settings for Inspection Lot (QM View)

### 1. Inspection Type Details

Field	Required Value
Inspection Type	01 (Goods Receipt Inspection)
Active	Yes
Automatic Inspection Lot Creation	Yes
Post to Inspection Stock	Yes

### 2. Additional Master Data (optional)

MIC – Master Inspection Characteristics

Qualitative characteristics

Quantitative characteristics

Sampling Procedure

Fixed sample size

Percentage sample

Inspection Plan

Optional for basic GR inspection

Required for complex characteristics

### 3. Partner Profile

Vendor

QM Info Record (QI01)