

This document lists all SAP transaction codes relevant to the **Basic Inspection Lot Creation & Processing** scenario. These T-codes cover master data setup, procurement integration, inspection lot execution, results recording, and usage decision.

1. Master Data (QM)

- MM03 – Display Material Master
- MM02 – Change Material Master (QM View)
- MM01 – Create Material Master
- QS21 – Create Inspection Plan
- QS22 – Change Inspection Plan
- QS23 – Display Inspection Plan
- QS31 – Create Master Inspection Characteristic
- QS32 – Change Master Inspection Characteristic
- QS33 – Display Master Inspection Characteristic
- QS41 – Create Sampling Procedure
- QS42 – Change Sampling Procedure
- QS43 – Display Sampling Procedure

2. Procurement & Goods Receipt (MM Integration)

- ME21N – Create Purchase Order
- ME22N – Change Purchase Order
- ME23N – Display Purchase Order
- MIGO – Goods Receipt (Triggers Inspection Lot for Type 01)

3. Inspection Lot Processing

- QA32 – Change/Display Inspection Lot
- QA02 – Change Inspection Lot
- QA03 – Display Inspection Lot
- QA11 – Record Usage Decision
- QA12 – Change Usage Decision
- QA13 – Display Usage Decision

4. Results Recording

- QE51N – Results Recording for Inspection Lot
- QE01 – Create Results Recording
- QE02 – Change Results Recording
- QE03 – Display Results Recording