

Rachet -

35

30

-25 -20

Barrel






Fig. 3.34 Universal vernier bevel protractor



Thread plug gauge



1 = distance between centres of ground cylinders (typically 5" or 10")

h = height of the gauge blocks o = the angle of the plate

 $\theta = \operatorname{asin}\left(\frac{h}{l}\right)$







Fig. 3.22. Vernier coliper-Type A.








Lathe Machine



Upright or column drilling machine







Pedestal Grinder

