REVISION HISTORY

DATE:	DESCRIPTION	REVISION
3/15/01	ADD D13,D14,R179,C86	2.0
6/18/01	DELETE D13,R179,R180-187,R188-195 RENAME V1.8A TO V2.0A RENAME VDDTX TO V2.0A RENAME V1.8 TO V2.0 CONNECT T6,T7 ALL CT TO V2.0A ADD 3.3V AND 2.5V OPTION FOR VIO	3.0
6/25/01	REPLACE U4,5 WITH MIC29302BT ADD 3.3/2.5V OPTIONS FOR VIO ADD MRXD0-3 10K PULL UP R202-205 ADD KS8999 T1, T5 PULL UP OPTION	3.1
7/25/01	JOIN MCOL AND MCOLIN (P.6)	3.2
7/01/02	REMOVE PORT TRUNKING TABLE REMOVE OSC1 TO 66MHz ADD NO CONNECTION ON PIN 174 & 175 RENAME LED8_1 TO RESERVED RENAME PIN 87, TEST[3] to AUTOMDIX	3.3
6/14/07	Change resistors and capacitors' value as below: R138 1.8K -> 1.43K for 2.1V R149 2.4K -> 2.49K for 3.3V R201 1.5K -> 1.54K for 2.5V C40/C41 22PF -> 18PF for Y1 25 MHz Crystal	3.4
4/17/08	Change resistor's value as below: R17 3K -> 3.01K 1%	3.5









