

Bunker Delivery Evidence Report

RPT-SES-2026-016-20260609T160053Z · generated 2026-06-09T16:00:53Z

VERDICT: REFUSE_TO_SIGN

Delivery

BDN reference	BDN-SG-2026-06-0016
Date	2026-06-10
Window	10:15:00 – 14:32:00
Port	Singapore, Eastern Anchorage
Vessel	EVER GIVEN (IMO 9776002)
Barge	ALLI
Supplier	BunkerGuard Demo Supplier Gamma Pte Ltd
Supplier licence	DEMO-MPA-LIC-003
Fuel grade	VLSFO RMG 380

Risk assessment

Final score	78/100
Category	CRITICAL
Recommended verdict	REFUSE_TO_SIGN
Similar incidents (30d)	0

Quantity comparison

BDN declared (MT)	500.0
MFM measured (MT)	481.2
Discrepancy (MT)	-18.8
Discrepancy (%)	-3.76
VLSFO spot (USD/MT)	585.0
Financial impact (USD)	10998

AI narrative

Critical quantity mismatch detected: MFM measured 481.2 MT against BDN declared 500.0 MT, representing a shortfall of 18.8 MT (-3.76%). This deviation exceeds the 0.5% tolerance threshold by 752% and violates MEPC.1/Circ.891 guidelines. The trajectory deviation pattern observed at 1.5 hours (10.3% below expected) indicates systematic under-delivery throughout the operation. Financial impact calculated at USD 10,998 based on VLSFO spot price of USD 585.0 per MT.

Anomalies — total 2 (critical 1, high 1, medium 0)

Rule	Sev	Time	Description
A01 Quantity Trajectory Deviation	HIGH	2026-06-10T11:45:00+00:00	Delivery 10.3% below trajectory at 1.5hr mark. Consistent with prior pattern.

Rule	Sev	Time	Description
A02 Quantity Final Mismatch	CRITICAL	2026-06-10T14:32:00+00:00	Final MFM 481.2 MT vs BDN 500.0 MT. Short 18.8 MT (3.76%). Est. impact: USD \$11,000.

Compliance flags

Check	Status
ais verified	PASS
grade matches brf	PASS
marpol sulphur ok	PASS
mpa licence valid	PASS
signatures complete	PASS
solas flash point ok	PASS
quantity within tolerance	FAIL

Recommended actions

1. Refuse to sign BDN-SG-2026-06-0016 until quantity discrepancy is resolved
2. Issue formal Letter of Protest citing MEPC.1/Circ.891 non-compliance
3. Demand supplier provide written explanation for 18.8 MT shortfall
4. Request MFM calibration certificates and flow meter verification records
5. Notify P&I; club and flag state of quantity mismatch exceeding tolerance

Letter of Protest (draft)

LETTER OF PROTEST

To: BunkerGuard Demo Supplier Gamma Pte Ltd
From: M/V EVER GIVEN (IMO: 9776002)
Date: 2026-06-10
Port: Singapore, Eastern Anchorage

Re: Bunker Delivery Note BDN-SG-2026-06-0016 - Quantity Discrepancy

We hereby formally protest the bunker delivery completed on 2026-06-10 from barge ALLI for the following reasons:

1. **QUANTITY MISMATCH:** Your BDN declares 500.0 MT of VLSFO RMG 380, however our calibrated Mass Flow Meter (MFM) recorded only 481.2 MT actually delivered, representing a shortfall of 18.8 MT (-3.76%).
2. **REGULATORY NON-COMPLIANCE:** This deviation exceeds the 0.5% tolerance specified in IMO MEPC.1/Circ.891 guidelines for bunker quantity verification.
3. **FINANCIAL IMPACT:** The quantity shortfall represents approximately USD 10,998 in value based on current VLSFO market rates.

We demand immediate rectification of this discrepancy before BDN acceptance. This protest is issued to preserve our rights under the bunker supply contract and applicable maritime law.

Chief Engineer: _____

Date: _____

Vessel Stamp: _____

session_id: SES-2026-016 · report_hash:
522f4cb92b6e6fbd961bddfe0c3cb9ccafb62eca2477be00edcdc360972b7cc5