

BUNKER DELIVERY

Evidence Report

Report ID **RPT-SES-2026-016-20260609T160053Z** · Issued **2026-06-09T16:00:53Z**

VERDICT • REFUSE TO SIGN

RISK 78/100 CRITICAL	QUANTITY DEVIATION -3.76% -18.8 MT · USD 10998	ANOMALIES 2 crit 1 · high 1 · med 0
---	---	--

1 Delivery Particulars

BDN reference	BDN-SG-2026-06-0016
Delivery date	2026-06-10
Delivery window	10:15:00 – 14:32:00
Port	Singapore, Eastern Anchorage
Receiving vessel	EVER GIVEN (IMO 9776002)
Delivering barge	ALLI
Supplier	BunkerGuard Demo Supplier Gamma Pte Ltd
Supplier licence	DEMO-MPA-LIC-003
Fuel grade	VLSFO RMG 380

2 Risk Assessment

Final risk score	78 / 100
Risk category	CRITICAL
Recommended verdict	REFUSE_TO_SIGN
Similar incidents (30d)	0

3 Quantity Comparison

BDN declared (MT)	500.0
MFM measured (MT)	481.2
Discrepancy (MT)	-18.8
Discrepancy (%)	-3.76
VLSFO spot (USD/MT)	585.0
Estimated financial impact (USD)	10998

4 AI Narrative



A Appendix — Letter of Protest (Draft)

LETTER OF PROTEST

To: BunkerGuard Demo Supplier Gamma Pte Ltd

From: M/V EVER GIVEN (IMO: 9776002)

Date: 2026-06-10

Port: Singapore, Eastern Anchorage

Re: Bunker Delivery Note BDN-SG-2026-06-0016 - Quantity Discrepancy

We hereby formally protest the bunker delivery completed on 2026-06-10 from barge ALLI for the following reasons:

1. **QUANTITY MISMATCH:** Your BDN declares 500.0 MT of VLSFO RMG 380, however our calibrated Mass Flow Meter (MFM) recorded only 481.2 MT actually delivered, representing a shortfall of 18.8 MT (-3.76%).
2. **REGULATORY NON-COMPLIANCE:** This deviation exceeds the 0.5% tolerance specified in IMO MEPC.1/Circ.891 guidelines for bunker quantity verification.
3. **FINANCIAL IMPACT:** The quantity shortfall represents approximately USD 10,998 in value based on current VLSFO market rates.

We demand immediate rectification of this discrepancy before BDN acceptance. This protest is issued to preserve our rights under the bunker supply contract and applicable maritime law.

Chief Engineer: _____

Date: _____

Vessel Stamp: _____