


## Octopus Learn To Solder Board Instructions




- 1) Bend eyebrow resistor wires. Insert and solder. Clip off excess leads.
  - 2) Insert two switches, solder four pins on each.
  - 3) Insert all LEDs by color. Make sure to put the long lead in the square hole. Solder. Clip off excess leads.




- 4) Insert battery holder, being sure to line up square section of holder outline with white mark on board, solder.
  - 5) Snap switch caps on top of switches.
  - 6) Insert battery (+ side up), press switches to test.
  - 7) Clip any pokey leads on back side (optional).

Octopus Learn To Solder Board Instructions




- 1) Bend eyebrow resistor wires, insert and solder. Clip off excess leads.
  - 2) Insert two switches, solder four pins on each.
  - 3) Insert all LEDs by color. Make sure to put the long lead in the square hole. Solder. Clip off excess leads.




- 4) Insert battery holder, being sure to line up square section of holder outline with white mark on board, solder.
  - 5) Snap switch caps on top of switches.
  - 6) Insert battery (+ side up), press switches to test.
  - 7) Clip any pokey leads on back side (optional).

## Octopus Learn To Solder Board Instructions




- 1) Bend eyebrow resistor wires, insert and solder. Clip off excess leads.
  - 2) Insert two switches, solder four pins on each.
  - 3) Insert all LEDs by color. Make sure to put the long lead in the square hole. Solder. Clip off excess leads.




- 4) Insert battery holder; being sure to line up square section of holder outline with white mark on board, solder.
  - 5) Snap switch caps on top of switches.
  - 6) Insert battery (+ side up), press switches to test.
  - 7) Clip any pokey leads on back side (optional).

## Octopus Learn To Solder Board Instructions




- 1) Bend eyebrow resistor wires, insert and solder. Clip off excess leads.
  - 2) Insert two switches, solder four pins on each.
  - 3) Insert all LEDs by color. Make sure to put the long lead in the square hole. Solder. Clip off excess leads.




- 4) Insert battery holder, being sure to line up square section of holder outline with white mark on board solder.**
  - 5) Snap switch caps on top of switches.**
  - 6) Insert battery (+ side up), press switches to test.**
  - 7) Clip any pokey leads on back side (optional).**

Octopus Learn To Solder Board Instructions




- 1) Bend eyebrow resistor wires. Insert and solder. Clip off excess leads.
  - 2) Insert two switches, solder four pins on each.
  - 3) Insert all LEDs by color. Make sure to put the long lead in the square hole. Solder. Clip off excess leads.




- 4) Insert battery holder; being sure to line up square section of holder outline with white mark on board solder.**
  - 5) Snap switch caps on top of switches.**
  - 6) Insert battery (+ side up), press switches to test.**
  - 7) Clip any pokey leads on back side (optional).**

Octopus Learn To Solder Board Instructions



- 1) Bend eyebrow resistor wires, insert and solder. Clip off excess leads.
  - 2) Insert two switches, solder four pins on each.
  - 3) Insert all LEDs by color. Make sure to put the long lead in the square hole. Solder. Clip off excess leads.



- 4) Insert battery holder, being sure to line up square section of holder outline with white mark on board solder.
  - 5) Snap switch caps on top of switches.
  - 6) Insert battery (+ side up), press switches to test.
  - 7) Clip any pokey leads on back side (optional).