

Sheet1

V1.1 is to solve the problem of Hotend port being continuously enabled in the STM32H723 version.

Changes in V1.1 compared to V1.0

Pinout changes

Name	Octopus Pro V1.0/V1.0.1	Octopus Pro V1.1
HE0	PA2	PA0
HE2	PB10	PB0
Motor3-EN	PA0	PA2
RGB	PB0	PB10

CAN bus interface sub model

Octopus Pro V1.0/V1.0.1	Octopus Pro V1.1
RJ11	XH2.54*2Pin

rsion dfu mode