AirSense 10 CPAP Machine

RETURNED EQUIPMENT: EXTERNAL CLEANING AND COMPONENT ROUTING

Document	Revision	Department	Status
SOP-CPAP-001	0.6	Sleep Equipment Services	DRAFT — NOT FOR CLINICAL USE

DRAFT — NOT APPROVED FOR CLINICAL USE. Use only after the hospital has approved the controlled cleaning product and its application instructions.

Purpose and scope

This procedure provides instructions for the external cleaning of returned ResMed AirSense 10 CPAP machines. It also specifies how technicians identify and route returned components for reprocessing, disposal or further assessment. This procedure applies to trained hospital technicians. It does not cover internal repair, patient-data management or authorization for patient reuse.

Materials, work areas and records

Item	Identification / location
PPE	Disposable nitrile gloves; disposable plastic apron. Follow local risk assessment for additional PPE.
Exterior cleaning	Disposable lint-free cloth; approved surface-cleaning product identified in REF-03; disposable dry cloth.
Work areas	AREA-01: contaminated returns; AREA-02: exterior cleaning; AREA-03: cleaned / awaiting assessment; AREA-04: fault isolation.
Component containers	BIN-01: reprocessing transfer; BIN-02: approved disposal route. Both require local confirmation.
Labels	LBL-001: equipment ID; LBL-002: exterior cleaning complete / NOT RELEASED; LBL-003: HOLD — DO NOT USE.
Records	FRM-001: AirSense 10 cleaning and routing record; FRM-002: equipment fault report.
Cleaning-method reference	REF-03 — AirSense 10 approved exterior-cleaning method. Specifies the product, concentration, contact time, application method and residue-removal requirements.

Safety



⚠ WARNING: ELECTRICAL HAZARD

1. Disconnect the power supply before cleaning.
2. Do not immerse the machine in water.
3. Do not immerse the machine in cleaning solution.
4. Keep liquid out of electrical connections.



MANDATORY — PERSONAL PROTECTIVE EQUIPMENT

1. Put on disposable nitrile gloves.
2. Put on a disposable plastic apron.



STOP WORK — DAMAGED OR UNIDENTIFIED EQUIPMENT

1. Stop the procedure.
2. Attach LBL-003.
3. Move the machine to AREA-04.
4. Record the fault on FRM-002.
5. Notify the equipment supervisor.

1 Receive and identify

1. Put the returned machine in AREA-01.
2. Read the model number on the device label.
3. Record the model number on FRM-001.
4. Read the serial number on the device label.
5. Record the serial number on FRM-001.
6. Record the receipt date on FRM-001.
7. Attach LBL-001 with the equipment tracking number.
8. Inspect the housing for visible damage.
9. Inspect the display for visible damage.
10. Inspect the power supply and power cord for visible damage.
11. Record damaged or missing items on FRM-001.



STOP WORK — DAMAGED OR UNIDENTIFIED MACHINE

1. Attach LBL-003.
2. Move the machine to AREA-04.
3. Complete FRM-002.
4. Notify the equipment supervisor.

2 Identify and route returned components

Use the table below. Do not put patient-contact accessories into the clean machine area. Component reprocessing must use the current ResMed Air10 clinical reprocessing addendum and the approved hospital procedure.

Component / identification	Required technician action
Cleanable humidifier / water tub	Confirm the component is the manufacturer-designated cleanable type. Put it in BIN-01 for validated reprocessing.
Standard water tub	Keep it out of the reprocessing route for multi-patient use. Follow the approved disposal or replacement instruction.
Air tubing / elbow	Read the component identifier. Match it to the approved reprocessing list. Put approved reusable components in BIN-01.
Air outlet	Do not remove without approved training. Refer the machine for the specified air-outlet reprocessing procedure.
Air filter	Identify the installed filter type. Follow the applicable approved replacement instruction.
Mask / headgear	Keep separate from the machine. Route according to the approved accessory-specific procedure.



STOP WORK: UNKNOWN PART

1. Stop the procedure.
2. Keep the unidentified component in AREA-01.
3. Record the unidentified component on FRM-002.
4. Notify the equipment supervisor.
5. Wait for instructions before continuing.

3 Clean the machine exterior

PRECONDITION — APPROVED CLEANING METHOD

REF-03 must specify the approved product, concentration, contact time, application method and residue-removal instructions.

1. Do not start cleaning without an approved REF-03 entry for the AirSense 10.
2. Move the identified machine to AREA-02.
3. Confirm that the power supply is disconnected.
4. Put on the required PPE.
5. Obtain the approved cleaning product specified in REF-03.
6. Compare the product name with REF-03.
7. Compare the product concentration with REF-03.
8. Check the required contact time in REF-03.
9. Clean the machine housing with the approved product.
10. Clean the display with the approved product.
11. Clean the permitted external surfaces according to REF-03.
12. Keep the treated surfaces wet for the verified contact time.
13. Remove residue only as specified in REF-03.
14. Allow the surfaces to dry.
15. Inspect the surfaces for visible contamination.
16. Inspect the machine for visible damage.



STOP WORK — CLEANING METHOD UNAVAILABLE OR RESULT UNSATISFACTORY

1. Stop the procedure.
2. Keep the equipment out of AREA-03.
3. Attach LBL-003.
4. Record the problem on FRM-002.
5. Notify the equipment supervisor.

4 Record, label and transfer

1. Record the cleaning date on FRM-001.
2. Record your technician ID on FRM-001.
3. Record the approved cleaning-method reference and revision on FRM-001.
4. Record the exterior inspection result on FRM-001.
5. Record the destination of each separated component on FRM-001.
6. Confirm that all required cleaning steps are complete.
7. Attach LBL-002 to the machine.
8. Move the machine to AREA-03.



RELEASE RESTRICTION

LBL-002 means exterior cleaning is complete.

Do not release the machine for patient use.

5 Technician completion record — FRM-001

Exterior inspection — PASS criteria

- The approved exterior-cleaning procedure is complete.
- No visible contamination remains.
- No visible damage is present.
- The required cleaning information is recorded.

Record **HOLD** when these criteria are not met.

Field	Technician entry
Equipment tracking ID / serial no.	_____
Model / receipt date	_____
Technician ID / cleaning date	_____
Cleaning method REF-03 revision	_____
Cleaning product / concentration	_____
Exterior inspection	☐ Pass ☐ Hold
Humidifier / tub route	☐ Reprocess ☐ Dispose ☐ Not returned
Tubing / elbow route	☐ Reprocess ☐ Not returned ☐ Hold
Air outlet / other accessories	_____
Fault report FRM-002 no.	_____
Machine label / destination	☐ LBL-002 → AREA-03 ☐ LBL-003 → AREA-04