SnapMaker - Robinson 3D

Print Summary

Task

Progress
0%

Layer
0 / 0.0

Print Progress 0.0 %

Print Details

Status	complete
Notifications	Printer is ready
Remaining Time	0h
Print Duration	0m
End Time	0h
Print Weight	0.000 m

Lifetime Usage

Totals Print Time	130h 25m 25s
Totals Filament Used	785.62 m
Totals jobs	68 Jobs