

CRMC MRI Safety Implant Reminders

Not all Mechanical Heart Valves and Rings are MR Safe, many are conditional. We need to follow manufacturer guidelines.

-If the screening sheet is marked heart valve we need to make an attempt to obtain make and model for research. If we cannot obtain information the patient should only be scanned on the 1.5 in Normal Mode.

Not all Stents are MR Safe.

-If stent is marked on the screening sheet additional questions need to be asked of the RN. Where are the stents?

Cardiac Stents

ARE the only stents we can scan with no questions

Carotid Stents

TRY to get Make and Model. If impossible, scan only on 1.5T in Normal Mode

Trunk and Peripheral Stents

TRY to get Make and Model and follow manufacture guidelines.

If unable to determine the Make and Model of stent please use guidelines below:

1. Determine location of Stent in Body (iliac, femoral, renal, etc.)
2. Is the stent going to be within direct RF exposure?

Approximately 30cm (12inches) above and below isocenter.

*If YES- Consult with a radiologist before proceeding - if cleared by radiologist scan 1w/kg

*If NO- 1.5 T only 2w/kg SAR Normal Mode

IVC FILTERS and TAVR

If unable to determine the Make and Model of IVC filter or TAVR please scan on 1.5T only 2w/kg SAR Normal Mode.

Leadless Pacemaker

We do NOT need a chest x-ray because there are no leads to clear. We will, as always, need the make, model, rate, and mode for the pacemaker.

VP SHUNTS

If the VP shunt is non programmable we are able to scan on them on the 1.5T or 3T without any information on the shunt.

If the VP shunt **IS** programmable then we will need the make and model of that shunt as well as pre and post skull x-rays. Make sure the x-ray is read before scanning the patient.

*If the information is completely unobtainable then we can have the ordering physician order the pre-shunt xray. **SOMETIMES** the radiologists are able to identify the make and model from those images.

IUD

Any IUDs implanted in the US are considered safe on the 1.5T Normal Mode.

Aortic Stent

TRY to get Make and Model. If impossible, scan only on 1.5T in Normal Mode

Loop recorders

TRY to get Make and Model. If impossible, we must verify that it is a Loop Reorder and not a Pacemaker. Once verified then you can scan only on the 1.5T in Normal Mode.