









LDA #7E

Q5

INCA

Q6

JMP 22

Q5

*FO*  
03  
08  
*E1*  
10  
24  
*FA*  
33  
22

-

-



38

10

24

F9

21

FA

23=38

24=10

25=24

26=F9

27=21

28=FA



Q4  $(Q_9 \cdot I_{DF})$   $M(PC) \rightarrow TA; PC+I \rightarrow PC, LD_{TA}; INC_{PC}; MR,$   
Q5  $(Q5 \cdot I_{DF})$   $M(PC) \rightarrow R; PC+I \rightarrow PC, LD_R; INC_{PC}; MR; f3; f0,$   
Q6  $(Q6 \cdot I_{DF})$   $R \rightarrow M(TA)$   $OE_R; g_{14} ; MW, NF$



05

07

EF

20

02

21

21

20

05

07

EF

20

02

21

21

20



OP | Adr | Data

if  $A - \#Data = 0$ :  
JMP Adr

- Q4  $(Q4 \cdot I_{EF})$   $M(PC) \xrightarrow{\text{M(Adr)}} R ; PC+1 \xrightarrow{\text{(Data)}} PC, LD_R; INC_{PC}; f_3; f_0; MR,$
- Q5  $(Q5 \cdot I_{EF})$   $M(PC) \xrightarrow{\text{M(Adr)}} T ; PC+1 \xrightarrow{\text{(Data)}} PC, MR; LD_T; INC_{PC},$
- Q6  $(Q6 \cdot I_{EF})$   $A - T; ALU(z) \xrightarrow{\text{M(Adr)}} CC ; f_3; f_2; OE_A; g_0; LD_{CC}, g_9; g_8; g_5; g_4; g_3; g_2$
- Q7  $(Q7 \cdot I_{EF})$  if  $(z = 1)$   $M(R) \xrightarrow{\text{M(Adr)}} PC ; OE_R; LD_{SP} \cdot z$

