




SHUNT: OPO1 TP7


SHUNT


## VBUS monitoring

















Have removed jumpers for space

Diode transitor current sense from rp2040 motor driver







Replace jumper with pass throung