

SCANSNC CREATIVITY ANTHOLOGY
CO.,LTD.**QC**

CORRECTIVE ACTION REQUEST

CAR No.: CAR-2512-004/Rev.00

Date: 11/12/2025

Page: 1 of 1


Name:	verymaron01	Position:	
Line:		Company:	SNC CREATIVITY ANTHOLOGY CO.,LTD.
Part No:	P0030245	Part Name:	P0030245
Model:		Lot No:	December
Invoice No:		Q'ty:	30

Originator (ผู้จัดทำ): [] Customer [] QC [] Maintenance [] Other

1. Problem Description (รายละเอียดปัญหา):

ปัญหาจากการขันย้าย เกิดการเลี้ยวซ้ายเกิดรอยบุบ

Defect Type: Dent

**2. Containment Action (การแก้ไขเบื้องต้น): (Within 7 Days reply)**

อบรมพนักงานส่งสินค้า

3. Root Cause Analysis (สาเหตุของปัญหา):

[X] Man [] Machine [] Material [] Method [] Other

ยกของโดยความประมาท ทำให้งานไม่ไปชนกัน

4. Leak Cause (สาเหตุที่หลุดรอด):

ตรวจสอบไม่ทั่วถึง

5. Corrective Action (การแก้ไขระยะยาว):

เพิ่มการตรวจสอบและมาตรฐานการขันส่ง

6. Verification of Effectiveness: (If found reoccurrence, back to re-analysis)

1. Prod Date: _____ [] Accept [] Reject, need back to analysis element no.2

2. Prod Date: _____ [] Accept [] Reject, need back to analysis element no.3

3. Prod Date: _____ [] Accept [] Reject, need back to analysis element no.4

7. Summary Standardization Effectives:

[] Update FMEA [] Update Control Plan [] Update Work Instruction [] Others:

Report By	Check By	Ack. By (QMR)
(verymaron01) Date: 11/12/2025 (QC Supervisor) Date: ____ / ____ / ____ (QMR) Date: ____ / ____ / ____