BL
LOUTA MINE | LOUTA BENEFICIATION

110LG-RC-01 PHOSPHATE ORE RECLAIMER
110LG-CV-01 PHOSPHATE ORE CONVEYOR
110LG-CV-02 PHOSPHATE ORE CONVEYOR
110LG-WE-01 WEIGHTOMETER
110LG-TC-01 TRIPPER CONVEYOR
110LG-ST-01 SLEWING STACKER TYPE
110LG-BC-01 BOOM CONVEYOR OF RECLAIMER

PHOSPHATE ORE
B/LIMITS
FROM LOUTA MINE STOCKPILE 2 PHOSPHATE ORE
B/LIMITS
FROM LOUTA MINE

STORAGE AND HANDLING PACKAGE

BL 100 1
BL 101 1

110LG-RC-01
NOTE 11

110LG-BC-01
DETAIL 1C

A-1000
I 1003
ZA 990 (A-Y)
ZS 990 (A-Y)
BELT MISALIGNMENT (QTY x) (A-x)
HOLD 3
NOTE 9

NOTE 5
LA 250
LS 250

HA 901 (A-x)
STOP I 1004 A-1001
HS 901
SAFETY PULL CORD (QTY x)
HOLD 3
NOTE 10

ZS 946
ZA 946
HOLD 2

BLOCKED CHUTE
LSH 218
LAH 218
I 1026 A-1000

PRE-START ALARM
HORN & BEACON
XA 502
M
MCC
U1 502
A 1001 I-1004 STOP
STOP I 1009 A-1100 NOTE 11
A 1000 I-1001 I-1026 I-1002 I-1034 I-1003

ZS 991 RIP DETECTION
ZA 991
A-1000 I 1002

110LG-CV-01 (CB1)
GRAVITY TAKE-UP
SE 601 ZERO SPEED
NOTE 13
SSL 601
SAL 601
I 1001 A-1000 STOP CONVEYOR
ZSL 802
ZAL 802
ZSH 802
ZAH 802

STOP A-1000 I 1034
STOP A 1013 I-1015 I-1029 I-1027 I-1028 I-1033
PRE-START ALARM
HORN & BEACON
XA 585
U1 585
A 1014 STOP I-1030
MCC
M
HOLD 2
ZA 947
ZS 947
STOP A-1014 1030
HA 992 (A-x)
HS 992
SAFETY PULL CORD (QTY x)
HOLD 3
NOTE 9

NOTE 5
LA 251
LS 251

A-1013 I 1028
ZA 986 (A-Y)
ZS 986 (A-Y)
BELT MISALIGNMENT (A-x) (QTY x)
HOLD 3
NOTE 10

HOLD 4
MI 903
MT 903
MOISTURE ANALYZER
ME 903

NOTE 3
HOLD 1
AI 310
AIT 310
BPL ANALYZER
AE 310

RIP DETECTION
ZS 927
ZA 927
A-1013 I 1033

GRAVITY TAKE-UP
ZSH 804
ZAH 804
ZSL 804
ZAL 804

110LG-WE-01
WE 706
WAH 706
WI 706
WQI 706

NOTE 12 110LG-CV-02 (CB2)
ZERO SPEED
SE 611
SSL 611
SAL 611
A-1013 I 1027 STOP CONVEYOR

BLOCKED CHUTE
LSH 228
LAH 228
A-1013 I 1029

CCTV CAMERA
LAH 203
A-1003 I 1014
LSH 203
BLOCKED CHUTE
CHUTE

NOTE 5
A-1003 I 1817
LA 252
LS 252
A-1003 I 1012
ZA 928 (A-Y)
ZS 928 (A-Y)
BELT MISALIGNMENT (QTY x)
HOLD 3
HA 902 (A-x)
A-1004 I 1013
HS 902
SAFETY PULL CORD (QTY x)
HOLD 3

GRAVITY TAKE-UP
ZSL 805
ZAL 805
ZSH 805
ZAH 805
ZS 993
ZA 993
RIP DETECTION
A-1003 I 1019

110LG-TC-01 (SB1)
ZERO SPEED
SE 602
SSL 602
SAL 602
A-1003 I 1011 STOP CONVEYOR

HOLD 2
ZS 949
ZA 949
M
MCC
I-1013 A 1004
U1 503
XA 503
PRE-START ALARM
HORN & BEACON
I-1010 I-1011 I-1012 I-1014 I-1817
A 1003
A-1013 I 1015

NOTES 6 7
110LG-ST-01
NOTE 4
PHOSPHATE ORE STOCKPILE 1
PHOSPHATE ORE STOCKPILE 2

PHOSPHATE ORE
P.01d/0122LG
TO PHOSPHATE ORE STOCKPILE RECLAIMER

PHOSPHATE ORE
P.01d/0120LG
TO PHOSPHATE ORE STOCKPILE RECLAIMER

DETAIL 1C

NOTE 10
UA 913
I 1877 A-1138
US 913 SAFETY PULL CORD
SCREW TAKE-UP
ZSLL 848
ZALL 848
ZSHH 849
ZAHH 849
STOP CONVEYOR I 1873 A-1141
STOP CONVEYOR 1874 A-1141

STOP CONVEYOR
ZA 843
I 1872 A-1141
ZS 843 RIP DETECTION

110LG-WE-02
WE 790
WAH 790
WI 790
WQI 790

ZERO SPEED
SE 612
SSL 612
SAL 612

110LG-BC-01
A-1143 I 1875 STOP CONVEYOR

I-1872 I-1873 I-1874 I-1875 I-1876 STOP
A 1141 I-1877
A-1003 STOP I 1878
A 1141
U1 525
MCC
M
ZA 845
ZS 845

NOTE 9
ZS 844
BELT MISALIGNMENT
ZA 844
I 1876 A-1141

NOTES:

1) INST. TAG NUMBERS ARE PREFIXED WITH 110LG UNLESS NOTED OTHERWISE.
2) FUTURE FLEXIBILITY TO FEED DIRECTLY THE CORRIDOR.
3) ONLINE BPL ANALYZER INCLUDING PSD.
4) STACKER FULLY AUTOMATIC (THE LEVEL MEASUREMENT INSTRUMENT FOR THE STACKER SHOULD BE EQUIPPED WITH HIGH ALARM)
5) LEVEL INDICATOR TO DETECT THE PRESENCE OF MATERIAL. ULTRASONIC TYPE PROXIMITY SWITCHES.
6) WIND SPEED INDICATOR IS INSTALLED FOR SAFE OPERATION OF STACKER.
7) ANTI-COLLISION SYSTEM INSTALLED ON THE STACKER.
8) START SEQUENCE FOR ALL CONVEYORS: ONCE THE LOCAL OR REMOTE START BUTTON IS PRESSED A TIMER WILL ACTIVATE THE HORN AND FLASHING LIGHT FOR MINIMUM OF ONE (1) MINUTE PRIOR TO STARTING CONVEYOR.
9) THE FINAL NUMBER OF BELT MISALIGNMENT SENSORS WILL DEPEND ON THE FINAL LENGTH OF THE CONVEYOR. BELT ALIGNMENT SENSORS SHOULD BE LOCATED ON BOTH SIDES OF EACH CONVEYOR AND WIRED IN SERIES (I.E., LEFT TO DETECT AND ACT ON EITHER RIGHT OR LEFT SIDE OF BELT MISALIGNMENT).
10) THE FINAL NUMBER OF SAFETY PULL-CORD SWITCHES WILL DEPEND ON THE FINAL LENGTH OF THE CONVEYOR. SAFETY PULL-CORD SHOULD BE LOCATED ON BOTH SIDES OF EACH CONVEYOR AND WIRED IN SERIES.
11) THE ACTION A-1100 IS TO STOP THE RECLAIMER IN CASE OF THE TRIP OF THE CONVEYOR 110LG-CV-01.
12) VOLUME SCANNER & SAMPLER DEVICE WITH RECIRCULATION SYSTEM TO BE CONSIDERED.
13) MAGNETIC SEPARATOR AND METAL DETECTOR TO BE CONSIDERED ON CONVEYOR CB1.

HOLDS:

1) THE APPROPRIATE TECHNOLOGY FOR THIS APPLICATION TO BE CONFIRMED WITH VENDORS.
2) THE INSTRUMENT SWITCH SHOULD DETECT REVERSE MOVEMENT OF THE BELT.
3) NUMBER OF QUANTITY TO BE CONFIRMED.
4) THE APPROPRIATE MOISTURE ANALYSER TO BE INVESTIGATED.

No.	Date Issue	Issue / Description	Made by	Checked by	Approved by
1	26 Mar 2025	ISSUED FOR DESIGN	L.ABOU	M.BOUN	Z.LARG
0B	19 Mar 2025	ISSUED FOR HAZOP	M.BOUN	S.AHAN	Z.LARG
0A	20 Jan 2025	ISSUED FOR HAZOP	M.BOUN	S.AHAN	Z.LARG
0	03 MAY 2023	ISSUED FOR INTERNAL REVIEW	F.KOUAD	S.AHANC	Z.LARG

Groupe OCP

OCP
STORAGE & HANDLING
LOUTA BENEFICIATION PLANT

JESA

THIS DRAWING IS THE EXCLUSIVE PROPERTY OF JESA IT IS NOT TO BE REPRODUCED, COPIED, OR MODIFIED,EXCEPT BY WRITTEN AGREEMENT WITH JESA.

PIPING & INSTRUMENTATION DIAGRAM

0110LG : PHOSPHATE ORE STORAGE

PID NUMBER:	P.01d/0110LG					
SIZE	SCALE		PROJECT	PHASE	DOCUMENT	FOLIO	ISSUE
A0		JESA NUMBER:	Q8013012	III	Q80130-LOU-L02-PR-PID-0001		1