

Aurora Home — Security Advisory

AH-SA-2026-01

Pairing token reuse on the local network · published 24 March 2026

Summary

A device pairing token generated by the hub remained valid after pairing completed, and was accepted again for up to 24 hours. An attacker already on the same local network could use a captured token to pair an unauthorised device to the hub. The issue is fixed in firmware 4.3.

Severity

Rated moderate. Exploitation requires prior access to the local network and the ability to observe the pairing exchange, and yields the ability to add a device rather than to read existing data or control heating directly.

Affected firmware	Status	Action
4.3 and later	not affected	none
4.2.x	affected	update to 4.3
4.1.x	affected	update to 4.3
4.0.x	affected	update to 4.3
3.9 and earlier	affected, unsupported	replace or update; 3.x is out of support

What was changed

Pairing tokens are now single-use and expire 90 seconds after they are issued, matching the pairing timeout. The hub additionally rejects a pairing attempt from a device identifier that is already present in its table.

What you should do

Hubs update themselves overnight; no action is required beyond letting the update apply. Confirm the running version in the app under Settings. If a maintenance window is configured, the update applies inside that window, which can delay it by up to a day.

Review the device list after updating. A device you do not recognise should be removed and the incident reported through support.

Detection

Unauthorised pairing appears in the hub event log as a pairing event outside the window in which you were pairing something. The log retains 90 days.

Credit

Reported through the coordinated disclosure process. No exploitation in the field has been observed.