Electrical Rules Check Report

Class	Document	Message
Warning	Schieberegister_Trägerplatine.SchDo	Net CLK has no driving source (Pin U_SR-2, Pin X_In-6, Pin X_Out-3)
Warning	C Schieberegister_Trägerplatine.SchDo	Net R_Photo_1 has no driving source (Pin R101-2, Pin U_1-8, Pin X_Data_14-1)
Warning	Schieberegister_Trägerplatine.SchDo	Net R_Photo_2 has no driving source (Pin R102-2, Pin U_1-10, Pin X_Data_14-3)
Warning	Schieberegister_Trägerplatine.SchDo	Net R_Photo_3 has no driving source (Pin R103-2, Pin U_2-6, Pin X_Data_14-5)
Warning	Schieberegister_Trägerplatine.SchDo	Net R_Photo_4 has no driving source (Pin R104-2, Pin U_2-4, Pin X_Data_14-7)
Warning	Schieberegister_Trägerplatine.SchDo c	Net R_Photo_5 has no driving source (Pin R105-2, Pin U_2-8, Pin X_Data_58-15)
Warning	Schieberegister_Trägerplatine.SchDo	Net R_Photo_6 has no driving source (Pin R106-2, Pin U_2-10, Pin X_Data_58-13)
Warning	Schieberegister_Trägerplatine.SchDo	Net R_Photo_7 has no driving source (Pin R107-2, Pin U_1-4, Pin X_Data_58-11)
Warning	Schieberegister_Trägerplatine.SchDo c	Net R_Photo_8 has no driving source (Pin R108-2, Pin U_1-6, Pin X_Data_58-9)
Warning	Schieberegister_Trägerplatine.SchDo	Net Serial_In has no driving source (Pin R_PullDown_SER-2, Pin U_SR-10, Pin X_In-4)
Warning	Schieberegister_Trägerplatine.SchDo	Net Serial_Shift has no driving source (Pin U_SR-1, Pin X_In-2, Pin X_Out-7)
Warning	Schieberegister_Trägerplatine.SchDo	Net V_Ref has no driving source (Pin R10-1, Pin R11-2, Pin U_1-5, Pin U_1-7, Pin U_1-9, Pin U_1-11, Pin U_2-5, Pin U_2-7, Pin U_2-9, Pin U_2-11)
Warning	Schieberegister_Trägerplatine.SchDo c	Off grid Net Label LED5 at 152.4mm,129.42mm
Warning	Schieberegister_Trägerplatine.SchDo	Off grid X_Data_14 at 154.94mm,180.8mm
Warning	Schieberegister_Trägerplatine.SchDo	Off grid X_Data_58 at 132.08mm,150.32mm

Sonntag 19 Jan 2025 2:22:16 PN. Page 1 of 1