- \* Step 2. Plug the battery into the JST port or plug other power source into port IN.
  \* Step 3. Plug the Grove Coulomb Counter 3.3V to 5V (LTC2941) to port I<sup>2</sup>C of Grove-Base
  - Shield.
  - Step 4. Plug Grove Base Shield into Seeeduino.

\* Step 1. Plug the load or charger into the port OUT.

Step 5. Connect Seeeduino to PC via a USB cable.