## CT&DT-SPSU-"INNOVATOR'S"-TASK#01

TASK#01 - PRODUCT FAILURE ANALYSIS

PRODUCT - SONY BETAMAX

LAUNCHED -1975

DOWNFALL - 2015

FAILURE REASONS:

- 1. PRICE IS HIGH
- 2. RECORDING TIME
- 3. HIGH COST
- 4. PROPRIETERY TECHNOLOGY
- 5. LASER BASED TECHNOLOGY

PRODUCT - TATA DOCOMO

LAUNCHED - 2009

DOWNFALL - 2019

FAILURE REASONS:

- 1. MARKET COMPETITION
- 2. FINANCIAL ISSUES
- 3. LATE SHIFT FROM THE FALLING "COMA" TECHNOLOGY.
- 4. NO PROPER SIGNAL TOWERS

PRODUCT - AMAZON FIRE PHONE

LAUNCHED - 2014

DOWNFALL -

FAILURE REASONS:

- 1. LIMITED APP SELECTION
- 2. PRICE AND MARKETING
- 3. OPERATING SYSTEM
- 4. COMPETITION
- 5. CARRIER EXCLUSIVITY

PRODUCT - POWER MAC G4 CUBE

LAUNCHED -July-19- 2000

DOWNFALL - July -3-2001

FAILURE REASONS:

- 1.THE CUBE DESIGN WAS DIFFERENT FROM CONVENTIONAL COMPUTERS
- 2. PERFORMANCE ISSUES
- 3. OVER HEATING
- 4. MARKETING AND DISTRIBUTION
- 5. EXPANSION

LAUNCHED - 2006 DOWNFALL - 2010

## FAILURE REASONS:

- 1. LATE ENTRY INTO THE MARKET
- 2. POOR MARKETING AND BRAND PERCEPTION
- 3. COMPATIBILITY ISSUES
- 4. LIMITED GLOBAL AVAILABILITY
- 5. LIMITED APP ECOSYSTEM

## TEAM MEMBERS:

S.PRASAD
S.AKHIL
S.DURGA PRASAD
A.VISHNUVARDHAN MANI
V.VIJAY KUMAR