

FIELD SERVICE REPORT

 SMARTFIX AUTOMATION No. 5/12, Chetty Street, Poonamallee, Chennai, Tamil Nadu - 600056 Mail: csm@smartfixautomation.com +91 9894571542		FSR No: FSR2026-102		Date: 30/09/2026		
		Ref.No: —		Start Date: —		
		End Date: —				
		Visit Type ☒ Chargeable Non Chargeable				
Customer Details: rockwell ponnamalle chennai LOCATION: —		Category ☒ Service Emc Project Warranty Demo/Training System Study				
Contact Person Name: selva Mobile: 74108520963 EMAIL: selvarajs02@gmail.com						
Customer Issue:		• Here are concise templates tailored for industrial automation field service reports (specifically for PLC troubleshooting, commissioning, or project work) that align with your report fields:•				
Action:		• PLC communication failure on main line; machine intermittent tripping on safety fault. • Line stopped due to Processor Major Fault (Code: Type 01, Code 60 / connection timeout to Remote I/O). • PLC communication failure on main line; machine intermittent tripping on safety fault. • Line stopped due to Processor Major Fault (Code: Type 01, Code 60 / connection timeout to Remote I/O). • PLC communication failure on main line; machine intermittent tripping on safety fault. • Line stopped due to Processor Major Fault (Code: Type 01, Code 60 / connection timeout to Remote I/O).				
Call Status:		Completed		☒ Pending Spare Required		
Spare Details: —						
Customer Feedback:		Extremely Satisfied		☒ Satisfied Dissatisfied		
Billing Details	No. of Persons	Total No. of Working Days	Over Time (Hrs)	Extra MAN Days (Over Time)	Total No. of MAN Days	Total No. of Payable Days
	1	1	1	1	1	1
<u>Customer Remarks:</u> PLC communication failure on main line; machine intermittent tripping on safety fault. Line stopped due to Processor Major Fault (Code: Type 01, Code 60 / connection timeout to Remote I/O). Name: Selva S Date: 30/09/2026  Signature & Seal			<u>Engineer's Remarks:</u> PLC communication failure on main line; machine intermittent tripping on safety fault. Line stopped due to Processor Major Fault (Code: Type 01, Code 60 / connection timeout to Remote I/O). Name: Admin Date: 30/09/2026  Signature			