

View from Top side (Scale 5:1)




Battery Leads

1	+ of the Battery
2	- of the Battery



Curved batteries can be welded by soldering or laser welding.

- Soldering is done at 360 degrees and completed within 3 seconds.
- Laser welding needs to be tuned according to the assembly factory's welding equipment, with no universal standard. Most importantly, the welding temperature and duration must be well



SensWear-V1R1

Designer/Engineer Yusein Ali	Board Title SensWear-Hub		
Drawn By Yusein Ali	Document Name SensWear-V1R1-MainBoard-		
Approved By Dariush Salami	Ver. 1	Rev. C0	Date 31.08.2026