
VESTA 1WS

extrusion preparation





Feed hole always on the right (facing back of the fixture) unless instructed otherwise by client.

OTHER LENGTH:

