



LUFTHAVNSVEJ 34-38
ROSKILDE, 4000
DENMARK

18 September, 2026

Telephone: +45 46191114

Fax:

Scan Criteria

Tail Number: OY-CAT

Tail Number: OY-CAT

Model: BN2B-26

Manufacturer: Britten-Norman

Description: ISLANDER

Total Hours: 13,709.45

Hours at Install:

Total Cycles: 19,988.00

Current Hours: 13,709.45

Event	Event Description	ATA	Status	Frequency	Last Compliance	Remaining	Compliance Due
CAT Practice	CAT practice tasks.		Optional	50,00H(+5,00)	13.680,90h/ 20-08-2026	21,45h	13.730,90h
Inspection	Pitot/static test.		Mandatory	24m(1m)	13.316,50h/ 05-12-2025		
Inspection	ARC full documented review.		Mandatory				
Inspection	Check Certificate of Insurance		Mandatory	12m(1m)	13.316,50h/ 05-12-2025		
Inspection	AMP review.		Mandatory	12m	13.331,50h/ 13-03-2026	5.84month	13-03-2027
CAT Practice	Maintenance documentation needs to be sent to CAT CAMO within 72 hours after aircraft has been released.		Mandatory	50,00H	13.680,90h/ 20-08-2026	21,45h	13.730,90h
Service Bulletin	Upper nose longeron inspection.		Mandatory	24cm	13.316,50h/ 19.314,00C/ 05-12-2025	15.42month	31-12-2027
Inspection	ARC extension.		Mandatory				
Inspection	Compass compensation.		Mandatory				
Inspection	Compass calibration, 36M.		Mandatory	36cm	13.316,50h/ 05-12-2025	27.42month	31-12-2028
Inspection	Continuous inspection of RH horizontal stab. inner rib after corrosion removal. Check condition.		Mandatory	1.000,00H 12cm	13.316,50h/ 05-12-2025	607,05h/ 3.42month	14.316,50h/ 31-12-2026
Inspection	Read out cabin heater hour meter and note time on work order.		Mandatory	50,00H	13.680,90h/ 20-08-2026	21,45h	13.730,90h
Inspection	Inspect seat belts in cockpit and cabin.		Mandatory	6cm	13.499,40h/ 07-07-2026	4.42month	31-01-2027
Inspection	Inspect overvoltage relays.		Mandatory	12cm	13.316,50h/ 05-12-2025	3.42month	31-12-2026
Inspection	Clean vacuum line deice filters LH/RH.		Mandatory	12cm	13.316,50h/ 05-12-2025	3.42month	31-12-2026
Inspection	Whelen landing and taxi light inspection IAW. STC ICA manual no. AML-140212. Perform function check. Check that all LEDs are illuminated. Inspect lens form abrasion, crazing or cracking. Check mounting connections and wire integrity.		Mandatory	12cm	13.316,50h/ 05-12-2025	3.42month	31-12-2026



LUFTHAVNSVEJ 34-38
ROSKILDE, 4000
DENMARK

18 September, 2026

Telephone: +45 46191114

Fax:

Tail Number: OY-CAT		Manufacturer: Britten-Norman		Model: BN2B-26		Description: ISLANDER	
Event	Event Description	ATA	Status	Frequency	Last Compliance	Remaining	Compliance Due
Inspection	Engine mount inspection at engine removal / 2000H, Britten-Norman.		Mandatory	2.000,00H 14 4cm	13.024,10h/ 02-08-2024	1.314,65h/ 119.42month	15.024,10h/ 31-08-2036
Inspection	Main battery capacity test, 6M.		Mandatory	6cm	13.426,00h/ 27-05-2026	2.39month	30-11-2026
CAT Practice	Avionics check iaw. CAT avionics ramp test report.		Recommended	12cm	13.316,50h/ 05-12-2025	3.42month	31-12-2026
Inspection	500 hour lubrication.		Mandatory	500,00H 12cm	13.316,50h/ 05-12-2025	107,05h/ 3.42month	13.816,50h/ 31-12-2026
Inspection	Update dent and buckle chart.		Mandatory	100,00H(+10, 00)	13.680,90h/ 20-08-2026	71,45h	13.780,90h
Inspection	Perform aircraft weighing and CG calculation, 48M.		Mandatory	60cm	12.561,50h/ 04-04-2024	31.39month	30-04-2029
Safety Information Bulletin	Test transponder altitude encoder every 24M.		Mandatory	24cm	13.316,50h/ 05-12-2025	15.42month	31-12-2027
Airworthiness Directive	Inspect passenger seat frames after 100H/100 landings.		Mandatory	100,00H 100, 00C	13.680,90h/ 19.939,00C/ 20-08-2026	71,45h/ 51,00C	13.780,90h/ 20.039,00C
Airworthiness Directive	Inspect horizontal stabiliser attachment bolts/anchor nuts.		Mandatory	1.000,00H	12.923,00h/ 13-12-2024	213,55h	13.923,00h
Service Bulletin	Check/calibrate engine tachometers.		Mandatory	12cm	13.316,50h/ 19.314,00C/ 05-12-2025	3.42month	31-12-2026
Service Bulletin	Inspect tailplane skin/structure for loose rivets and damage.		Mandatory	500,00H	13.316,50h/ 19.314,00C/ 05-12-2025	107,05h	13.816,50h
Service Bulletin	Inspect aircraft primary structure for corrosion.		Mandatory	24cm	13.316,50h/ 19.314,00C/ 05-12-2025	15.42month	31-12-2027
Service Bulletin	Examine nacelle box structure at MLG bottom fitting for cracks.		Mandatory	500,00H	13.316,50h/ 19.314,00C/ 05-12-2025	107,05h	13.816,50h
Service Bulletin	Inspect wing spar caps for cracks.		Mandatory	500,00H	13.316,50h/ 19.314,00C/ 05-12-2025	107,05h	13.816,50h
Service Bulletin	Examine control column sliding-tube for wear.		Mandatory	500,00H	13.316,50h/ 19.314,00C/ 05-12-2025	107,05h	13.816,50h
Service Bulletin	Inspect elevator outboard-hinge inboard-bracket for loose rivets/cracks/damage.		Mandatory	1.000,00H	12.923,00h/ 13-12-2024	213,55h	13.923,00h



LUFTHAVNSVEJ 34-38
ROSKILDE, 4000
DENMARK

18 September, 2026

Telephone: +45 46191114

Fax:

Tail Number: OY-CAT		Manufacturer: Britten-Norman		Model: BN2B-26		Description: ISLANDER	
Event	Event Description	ATA	Status	Frequency	Last Compliance	Remaining	Compliance Due
Service Bulletin	Inspect engine mounting brackets for cracks.		Mandatory	500,00H 1.00 0,00C	13.316,50h/ 19.314,00C/ 05-12-2025	107,05h/ 326,00C	13.816,50h/ 20.314,00C
Service Bulletin	Remove control surfaces and inspect attachment/hinge points on control surfaces and airframe.		Recommended	24cm	13.316,50h/ 19.314,00C/ 05-12-2025	15.42month	31-12-2027
Service Bulletin	Inspect the rudder final drive rod assembly.		Recommended	1.000,00H	12.923,00h/ 13-12-2024	213,55h	13.923,00h
Service Bulletin	Apply corrosion preventative fluid to internal airframe areas.		Optional	24cm	13.316,50h/ 19.314,00C/ 05-12-2025	15.42month	31-12-2027
Inspection	Cleaning and inspection of oil cooling system.		Mandatory	2.000,00H 14 4cm	12.795,20h/ 02-08-2024	1.085,75h/ 119.42month	14.795,20h/ 31-08-2036
Airworthiness Directive	Inspect elevator final drive control rod for internal corrosion.		Mandatory	24m	13.316,50h/ 05-12-2025	14.58month	05-12-2027
Inspection	100 hour inspection.		Mandatory	100,00H 12cm	13.680,90h/ 20-08-2026	71,45h/ 11.42month	13.780,90h/ 31-08-2027
Inspection	100 hour lubrication.		Mandatory	100,00H 12cm	13.680,90h/ 20-08-2026	71,45h/ 11.42month	13.780,90h/ 31-08-2027
Inspection	1000 hour lubrication.		Mandatory	1.000,00H 12c m	13.316,50h/ 05-12-2025	607,05h/ 3.42month	14.316,50h/ 31-12-2026
Inspection	Annual inspection.		Mandatory	1.000,00H 12c m	13.316,50h/ 05-12-2025	607,05h/ 3.42month	14.316,50h/ 31-12-2026
Inspection	50 hour inspection.		Mandatory	50,00H 4cm	13.680,90h/ 20-08-2026	21,45h/ 3.42month	13.730,90h/ 31-12-2026
Inspection	50 hour lubrication.		Mandatory	50,00H 12cm	13.680,90h/ 20-08-2026	21,45h/ 11.42month	13.730,90h/ 31-08-2027
Inspection	500 hour inspection.		Mandatory	500,00H 12cm	13.316,50h/ 05-12-2025	107,05h/ 3.42month	13.816,50h/ 31-12-2026
Inspection	Inspection of cabin heater, 100H.		Mandatory	100,00H 12cm	05-12-2025	3.42month	31-12-2026
Inspection	Cabin heater pressure decay test.		Mandatory	48cm	05-12-2025	39.42month	31-12-2029
Overhaul	Cabin heater overhaul.		Recommended	2.000,00H 12 0cm	22-12-2023	87.42month	31-12-2033
Airworthiness Directive	Inspect heater after 250H/24M		Mandatory	250,00H 24cm	05-12-2025	15.42month	31-12-2027
Overhaul	Overhaul every 1000 component tach hours		Mandatory	1.000,00H	22-12-2023		
Inspection	Inspection of cabin heater, 250H.		Mandatory	250,00H 12cm	05-12-2025	3.42month	31-12-2026
Overhaul	Cabin heater overhaul.		Recommended	2.000,00H 12 0cm	-1.182,75h/ 22-12-2023	817,25h/ 87.42month	817,25h/ 31-12-2033
Inspection	Inspection of cabin heater, 100H.		Mandatory	100,00H 12cm	1.331.690,00h/ 05-12-2025	1.331.790,00h/ 3.42month	1.331.790,00h/ 31-12-2026



LUFTHAVNSVEJ 34-38
ROSKILDE, 4000
DENMARK

18 September, 2026

Telephone: +45 46191114

Fax:

Tail Number: OY-CAT		Manufacturer: Britten-Norman		Model: BN2B-26		Description: ISLANDER	
Event	Event Description	ATA	Status	Frequency	Last Compliance	Remaining	Compliance Due
Replacement	Replace Instrument Air Filter		Mandatory	500,00H(+10,00) 12m(1mcumulative)	-389,25h/ 05-12-2025	110,75h/ 2.58month	110,75h/ 05-12-2026
Replacement	Overhaul of MLG and NLG.		Mandatory	72cm	22-12-2021	15.42month	31-12-2027
Replacement	Overhaul of MLG and NLG.		Mandatory	72cm	22-12-2021	15.42month	31-12-2027
Replacement	Overhaul of MLG and NLG.		Mandatory	72cm	22-12-2021	15.42month	31-12-2027
Inspection	Annual inspection of ELT.		Mandatory	12m	05-12-2025	2.58month	05-12-2026
Inspection	Perform weighing and inspection of fire extinguisher.		Mandatory	100,00H 12cm	1.333.090,00h/ 06-03-2026	1.333.190,00h/ 6.42month	1.333.190,00h/ 31-03-2027
Replacement	Replace fire extinguisher.		Mandatory	120m	-375,25h/ 06-03-2026	113.61month	06-03-2036
Replacement	Replace FAK Niveau 2		Mandatory				
Replacement	Replace FAK Niveau 3		Mandatory				
Inspection	Life vest visual inspection.		Mandatory	12cm	-389,25h/ 05-12-2025	3.42month	31-12-2026
Replacement	Life vest replacement.		Mandatory	120m	-3.264,75h/ 08-04-2019	30.68month	08-04-2029
Replacement	Life vest replacement.		Mandatory	120m	-3.264,75h/ 08-04-2019	30.68month	08-04-2029
Inspection	Life vest visual inspection.		Mandatory	12cm	-389,25h/ 05-12-2025	3.42month	31-12-2026
Replacement	Life vest replacement.		Mandatory	120m	-3.264,75h/ 08-04-2019	30.68month	08-04-2029
Inspection	Life vest visual inspection.		Mandatory	12cm	-389,25h/ 05-12-2025	3.42month	31-12-2026
Replacement	Life vest replacement.		Mandatory	120m	-3.264,75h/ 08-04-2019	30.68month	08-04-2029
Inspection	Life vest visual inspection.		Mandatory	12cm	-389,25h/ 05-12-2025	3.42month	31-12-2026
Replacement	Life vest replacement.		Mandatory	120m	-3.264,75h/ 08-04-2019	30.68month	08-04-2029
Inspection	Life vest visual inspection.		Mandatory	12cm	-389,25h/ 05-12-2025	3.42month	31-12-2026
Inspection	Life vest visual inspection.		Mandatory	12cm	-389,25h/ 05-12-2025	3.42month	31-12-2026
Replacement	Life vest replacement.		Mandatory	120m	-3.264,75h/ 08-04-2019	30.68month	08-04-2029



LUFTHAVNSVEJ 34-38
ROSKILDE, 4000
DENMARK

18 September, 2026

Telephone: +45 46191114

Fax:

Tail Number: OY-CAT		Manufacturer: Britten-Norman		Model: BN2B-26		Description: ISLANDER	
Event	Event Description	ATA	Status	Frequency	Last Compliance	Remaining	Compliance Due
Inspection	Life vest visual inspection.		Mandatory	12cm	-389,25h/ 05-12-2025	3.42month	31-12-2026
Replacement	Life vest replacement.		Mandatory	120m	-3.264,75h/ 08-04-2019	30.68month	08-04-2029
Replacement	Life vest replacement.		Mandatory	120m	-3.264,75h/ 08-04-2019	30.68month	08-04-2029
Inspection	Life vest visual inspection.		Mandatory	12cm	-389,25h/ 05-12-2025	3.42month	31-12-2026
Replacement	Life vest replacement.		Mandatory	120m	-3.264,75h/ 08-04-2019	30.68month	08-04-2029
Inspection	Life vest visual inspection.		Mandatory	12cm	-389,25h/ 05-12-2025	3.42month	31-12-2026
Inspection	Life vest visual inspection.		Mandatory	12cm	-389,25h/ 05-12-2025	3.42month	31-12-2026
Replacement	Life vest replacement.		Mandatory	120m	13-03-2018	17.84month	13-03-2028
Inspection	Life vest visual inspection.		Mandatory	12cm	-389,25h/ 05-12-2025	3.42month	31-12-2026
Replacement	Life vest replacement.		Mandatory	120m	09-02-2017	4.71month	09-02-2027
Airworthiness Directive	Inspect fuel injector fuel lines/clamps.		Mandatory	100,00H			
Airworthiness Directive	Inspect engine exhaust valves and guides.		Mandatory	330,00H			
Inspection	Cylinder pressure test.		Mandatory	100,00H(+10, 00)	20-08-2026		
Service Bulletin	Inspect exhaust valve/guide condition for wear or carbon build-up.		Mandatory	300,00H	02-08-2024		
Service Bulletin	Inspect intake pipe and flange for cracks/fuel staining.		Mandatory	50,00H			
Inspection	Engine internal corrosion inspection.		Optional	120m(1m)		93.45month	01-07-2034
Service Bulletin	Inspect intake/exhaust valves, springs, keys and rockers.		Mandatory	400,00H			
Inspection	Valve inspection; Remove rockerbox cover and check for freedom of valve rockers.		Mandatory	400,00H(+10, 00)	28-07-2026		
Airworthiness Directive	Hi-chrome valve guide inspection.		Mandatory	1.000,00H(+3 0,00)		1.086,00h	2.000,00h
Inspection	Engine overhaul.		Mandatory	2.000,00H(+2 00,00) 144m	02-08-2024	1.086,00h/ 118.48month	2.000,00h/ 02-08-2036
Inspection	Engine overhaul.		Mandatory	2.000,00H(+2 00,00) 144m	17-06-2025	1.315,00h/ 128.97month	2.000,00h/ 17-06-2037
Inspection	Valve inspection; Remove rockerbox cover and check for freedom of valve rockers.		Mandatory	400,00H(+10, 00)	27-05-2026		



LUFTHAVNSVEJ 34-38
ROSKILDE, 4000
DENMARK

18 September, 2026

Telephone: +45 46191114

Fax:

Tail Number: OY-CAT		Manufacturer: Britten-Norman		Model: BN2B-26		Description: ISLANDER	
Event	Event Description	ATA	Status	Frequency	Last Compliance	Remaining	Compliance Due
Airworthiness Directive	Hi-chrome valve guide inspection.		Mandatory	1.000,00H(+3 0,00)		1.315,00h	2.000,00h
Inspection	Cylinder pressure test.		Mandatory	100,00H(+10, 00)	20-08-2026		
Service Bulletin	Inspect exhaust valve/guide condition for wear or carbon build-up.		Mandatory	300,00H	17-06-2025		
Inspection	Engine internal corrosion inspection.		Optional	120m(1m)		104.77month	11-06-2035
Airworthiness Directive	Inspect engine exhaust valves and guides.		Mandatory	330,00H			
Service Bulletin	Inspect intake/exhaust valves, springs, keys and rockers.		Mandatory	400,00H			
Service Bulletin	Inspect intake pipe and flange for cracks/fuel staining.		Mandatory	50,00H			
Airworthiness Directive	Inspect fuel injector fuel lines/clamps.		Mandatory	100,00H			
Overhaul	Hartzell propeller overhaul.		Mandatory	2.400,00H 72 m	08-05-2026	1.924,00h/ 67.68month	2.400,00h/ 08-05-2032
Inspection	Inspect propeller blades, hub and visible parts for cracks, wear, corrosion and leaks.		Mandatory	100,00H 12cm		376,00h/ OVD58.58monthOVD	100,00h/ 31-10-2021
Inspection	Inspect propeller blades, hub and visible parts for cracks, wear, corrosion and leaks.		Mandatory	100,00H 12cm		4.42month	31-01-2027
Overhaul	Hartzell propeller overhaul.		Mandatory	2.400,00H 72 m	15-01-2026	63.9month	15-01-2032
Inspection	Alternator 500 hour inspection.		Mandatory	500,00H 24cm	27-05-2026	20.42month	31-05-2028
Overhaul	Alternator overhaul, 2000H/144M.		Mandatory	2.000,00H 14 4m	-914,00h/ 02-08-2024	1.086,00h/ 118.48month	1.086,00h/ 02-08-2036
Inspection	Alternator 100 hour inspection.		Mandatory	100,00H	20-08-2026		
Overhaul	Carburettor overhaul.		Mandatory	2.000,00H 14 4m	-685,00h/ 17-06-2025	1.315,00h/ 128.97month	1.315,00h/ 17-06-2037
Replacement	Replace engine attachment bolts.		Mandatory	2.000,00H 14 4cm	-914,00h/ 02-08-2024	1.086,00h/ 119.42month	1.086,00h/ 31-08-2036
Overhaul	Engine fuel pump overhaul.		Mandatory	2.000,00H 14 4cm	02-08-2024	119.42month	31-08-2036
Replacement	Engine flexible hoses replacement, 10 years		Mandatory	120m	-914,00h/ 02-08-2024	94.48month	02-08-2034
Overhaul	Magneto overhaul.		Mandatory	2.000,00H	-88,80h/ 08-04-2026	1.652,00h	1.911,20h
Inspection	Magneto 500 hour inspection.		Mandatory	500,00H(+10, 00)	-88,80h/ 08-04-2026	152,00h	411,20h
Overhaul	Magneto overhaul.		Mandatory	2.000,00H	-348,00h/ 08-04-2026	1.652,00h	1.652,00h

Aircraft Status



LUFTHAVNSVEJ 34-38
ROSKILDE, 4000
DENMARK

18 September, 2026

Telephone: +45 46191114

Fax:

Tail Number: OY-CAT		Manufacturer: Britten-Norman		Model: BN2B-26		Description: ISLANDER	
Event	Event Description	ATA	Status	Frequency	Last Compliance	Remaining	Compliance Due
Inspection	Magneto 500 hour inspection.		Mandatory	500,00H(+10, 00)	-348,00h/ 08-04-2026	152,00h	152,00h
Inspection	Start booster inspection.		Mandatory	500,00H		144,00h/ OVD	500,00h
Overhaul	Engine starter overhaul.		Mandatory	2.000,00H 14 4m	-694,00h/ 05-06-2025	1.306,00h/ 128.58month	1.306,00h/ 05-06-2037
Replacement	Vacuum pump replacement, 72M.		Mandatory	72m	12-09-2025	59.81month	12-09-2031
Inspection	Vacuum pump vane wear inspection.		Mandatory	100,00H(+10, 00) 12m	-28,30h/ 20-08-2026	71,70h/ 11.06month	71,70h/ 20-08-2027
Replacement	Vacuum relief filter replacement.		Mandatory	100,00H(+10, 00) 12m(1m)	-28,30h/ 20-08-2026	71,70h	71,70h
Replacement	Engine mount vibration isolator replacement.		Mandatory	2.000,00H 14 4cm	-914,00h/ 02-08-2024	1.086,00h/ 119.42month	1.086,00h/ 31-08-2036
Overhaul	Alternator overhaul, 2000H/144M.		Mandatory	2.000,00H 14 4m	-685,00h/ 17-06-2025	1.315,00h/ 128.97month	1.315,00h/ 17-06-2037
Overhaul	Carburettor overhaul.		Mandatory	2.000,00H 14 4m	-392,70h/ 05-12-2025	1.607,30h/ 134.58month	1.607,30h/ 05-12-2037
Replacement	Replace engine attachment bolts.		Mandatory	2.000,00H 14 4cm	-685,00h/ 17-06-2025	1.315,00h/ 129.39month	1.315,00h/ 30-06-2037
Overhaul	Engine fuel pump overhaul.		Mandatory	2.000,00H 14 4cm	17-06-2025	129.39month	30-06-2037
Replacement	Engine flexible hoses replacement, 10 years		Mandatory	120m	-685,00h/ 17-06-2025	104.97month	17-06-2035
Overhaul	Magneto overhaul.		Mandatory	2.000,00H	26-09-2025		
Inspection	Magneto 500 hour inspection.		Mandatory	500,00H(+10, 00)	08-04-2026		
Inspection	Magneto 500 hour inspection.		Mandatory	500,00H(+10, 00)	-209,70h/ 07-07-2026	290,30h	290,30h
Overhaul	Magneto overhaul.		Mandatory	2.000,00H	-209,70h/ 07-07-2026	1.790,30h	1.790,30h
Inspection	Start booster inspection.		Mandatory	500,00H		500,00h	500,00h
Overhaul	Engine starter overhaul.		Mandatory	2.000,00H 14 4m		2.000,00h	2.000,00h
Replacement	Vacuum pump replacement, 72M.		Mandatory	72m	21-07-2026	70.1month	21-07-2032
Inspection	Vacuum pump vane wear inspection.		Mandatory	100,00H(+10, 00) 12m	-28,20h/ 20-08-2026	71,80h/ 11.06month	71,80h/ 20-08-2027
Replacement	Vacuum relief filter replacement.		Mandatory	100,00H(+10, 00) 12m(1m)	-28,20h/ 20-08-2026	71,80h	71,80h
Replacement	Engine mount vibration isolator replacement.		Mandatory	2.000,00H 14 4cm	-685,00h/ 17-06-2025	1.315,00h/ 129.39month	1.315,00h/ 30-06-2037
Overhaul	Propeller governor overhaul.		Mandatory	2.000,00H 14 4m	27-05-2026	140.29month	27-05-2038



LUFTHAVNSVEJ 34-38
ROSKILDE, 4000
DENMARK

18 September, 2026

Telephone: +45 46191114

Fax:

Tail Number: OY-CAT		Manufacturer: Britten-Norman		Model: BN2B-26		Description: ISLANDER	
Event	Event Description	ATA	Status	Frequency	Last Compliance	Remaining	Compliance Due
Overhaul	Propeller governor overhaul.		Mandatory	2.000,00H 14 4m	17-06-2025	128.97month	17-06-2037
Replacement	Replace CO detector.		Mandatory	12m	13.316,50h/ 05-12-2025	2.58month	05-12-2026

*** End of Document ***