



LUFTHAVNSVEJ 34-38
ROSKILDE, 4000
DENMARK

18 September, 2026

Telephone: +45 46191114

Fax:

Scan Criteria

Tail Number:	OY-CDU
--------------	--------

Tail Number: OY-CDU

Model: TB-9

Manufacturer: Daher

Description: TB-9

Total Hours: 6,329.00

Hours at Install:

Total Cycles: 11,563.00

Current Hours: 6,329.00

Event	Event Description	ATA	Status	Frequency	Last Compliance	Remaining	Compliance Due
CAT Practice	CAT practice tasks.		Optional	50,00H(+5,00)	6.309,00h/ 13-07-2026	30,00h	6.359,00h
Inspection	Compass compensation.		Mandatory				
Inspection	Annual inspection.	05-20	Mandatory	12m(2mcumulative)	6.309,00h/ 13-07-2026	9.84month	13-07-2027
Inspection	2000 hour major inspection.	05-20	Mandatory	2.000,00H	5.939,70h/ 26-02-2024	1.610,70h	7.939,70h
Replacement	Brake hydraulic fluid replacement.		Mandatory	36cm(1m)	6.123,70h/ 25-04-2025		
Retirement	Wing assy retire.		Mandatory	14.600,00H		8.271,00h	14.600,00h
Inspection	Visual inspection of flap actuator, support and attach fittings.		Mandatory	500,00H	5.939,70h/ 26-02-2024	110,70h	6.439,70h
Inspection	Visual inspection of flap linkage.		Mandatory	1.000,00H	5.472,60h/ 28-12-2018	143,60h	6.472,60h
Inspection	Visual inspection of wing structure for corrosion.		Mandatory	2.000,00H 36cm	6.123,70h/ 25-04-2025	1.794,70h/ 19.39month	8.123,70h/ 30-04-2028
Inspection	Visual Inspection of wing spar flange/skin junction area, 2000H		Mandatory	2.000,00H 60m	5.939,70h/ 26-02-2024	1.610,70h/ 29.26month	7.939,70h/ 26-02-2029
Inspection	Inspect emergency equipment.		Mandatory	12m	6.268,40h/ 19-02-2026	5.03month	19-02-2027
Inspection	ARC extension.		Mandatory				
Inspection	ARC full documented review.		Mandatory				
Inspection	Check Certificate of Insurance		Mandatory	12m(1m)	6.267,00h/ 31-12-2025		
Inspection	Update dent and buckle chart.		Mandatory	100,00H(+10,00)	6.309,00h/ 13-07-2026	80,00h	6.409,00h
Inspection	Pitot/static test.		Mandatory	24m(1m)	6.282,10h/ 26-03-2026		
Inspection	Perform aircraft weighing and CG calculation (NON AOC TB Aircraft).		Mandatory	60m	5.921,30h/ 05-12-2022	14.58month	05-12-2027
CAT Practice	Avionics check iaw. CAT avionics ramp test report.		Recommended	12cm	6.268,40h/ 23-02-2026	5.32month	28-02-2027
Inspection	Compass compensation.		Mandatory	36cm	6.088,80h/ 17-02-2025	17.35month	29-02-2028
Service Bulletin	Front seats safety belts.		Mandatory	12m	6.268,40h/ 23-02-2026	5.16month	23-02-2027



LUFTHAVNSVEJ 34-38
ROSKILDE, 4000
DENMARK

18 September, 2026

Telephone: +45 46191114

Fax:

Tail Number: OY-CDU		Manufacturer: Daher		Model: TB-9		Description: TB-9	
Event	Event Description	ATA	Status	Frequency	Last Compliance	Remaining	Compliance Due
Service Bulletin	Inspect cabin access door hooks.		Optional	100,00H(+5,00) 12m(30d)	6.309,00h/ 13-07-2026	80,00h/ 6month	6.409,00h/ 18-03-2027
Service Bulletin	Rudder bearing visual inspection.		Mandatory	12cm	6.268,40h/ 23-02-2026	5.32month	28-02-2027
Service Bulletin	Pilot & co-pilot seat back inspection.		Mandatory	50,00H(+5,00) 12m(30d)	6.309,00h/ 13-07-2026	30,00h/ 6month	6.359,00h/ 18-03-2027
Airworthiness Directive	Inspect horizontal stabilizer internal structure.		Mandatory	72m	5.740,60h/ 30-11-2021	14.39month	30-11-2027
Airworthiness Directive	Wing front attachments inspection; wing and fuselage.		Mandatory	2.000,00H 3.000,00C	6.123,70h/ 10.681,00C/ 25-04-2025	1.794,70h/ 2.118,00C	8.123,70h/ 13.681,00C
Airworthiness Directive	Application of Kit OPT10911001 Wing Side Modification		Recommended				
Airworthiness Directive	Application of Kit OPT10919800 Fuselage Side Modification		Mandatory	8.000,00H 12.000,00C	6.123,70h/ 10.681,00C/ 25-04-2025	7.794,70h/ 11.118,00C	14.123,70h/ 22.681,00C
Inspection	AMP review.		Mandatory	12m	6.282,10h/ 08-04-2026	6.68month	08-04-2027
CAT Practice	Maintenance documentation needs to be sent to CAT CAMO within 72 hours after aircraft has been released.		Mandatory	50,00H	6.309,00h/ 13-07-2026	30,00h	6.359,00h
Inspection	Perform visual inspection of elevator hinge bearings.		Mandatory	1.000,00H		5.329,00h/ OVD	1.000,00h
Airworthiness Directive	Lower rudder hinge fitting inspection.		Mandatory	12cm	6.268,40h/ 23-02-2026	5.32month	28-02-2027
Airworthiness Directive	Gimbal joint inspection.		Mandatory	100,00H(+10,00)		6.229,00h/ OVD	100,00h
Inspection	50 hour inspection.	05-20	Mandatory	50,00H(+5,00) 6m(30dcumulative)	6.309,00h/ 13-07-2026	30,00h/ 3.84month	6.359,00h/ 13-01-2027
Inspection	100 hour inspection.	05-20	Mandatory	100,00H(+5,00)	6.309,00h/ 13-07-2026	80,00h	6.409,00h
Inspection	Cleaning and inspection of oil cooling system.		Mandatory	2.000,00H 144cm	4.976,60h/ 30-12-2015	647,60h/ 15.42month	6.976,60h/ 31-12-2027
Safety Information Bulletin	Test transponder altitude encoder every 24M.		Mandatory	24cm	6.282,10h/ 26-03-2026	18.42month	31-03-2028
Service Bulletin	Inspect horizontal stabilizer spar for corrosion.		Mandatory	72cm	5.740,60h/ 30-11-2021	14.39month	30-11-2027
Service Bulletin	Crack detection/inspection of wing front attachments.		Mandatory	2.000,00H 3.000,00C	5.872,20h/ 9.535,00C/ 22-07-2022	1.543,20h/ 972,00C	7.872,20h/ 12.535,00C



LUFTHAVNSVEJ 34-38
ROSKILDE, 4000
DENMARK

18 September, 2026

Telephone: +45 46191114

Fax:

Tail Number: OY-CDU		Manufacturer: Daher		Model: TB-9		Description: TB-9	
Event	Event Description	ATA	Status	Frequency	Last Compliance	Remaining	Compliance Due
Inspection	Compass calibration, 36M.		Mandatory	36cm	6.088,80h/ 17-02-2025	17.35month	29-02-2028
Inspection	Clean and inspect fuel selector filter.		Mandatory	100,00H 12m	6.123,70h/ 25-04-2025	105,30h/ OVD4.77monthOVD	6.223,70h/ 25-04-2026
Inspection	Cylinder pressure test.		Mandatory	100,00H(+10, 00)	13-07-2026		
Inspection	Valve inspection; Remove rockerbox cover and check for freedom of valve rockers.		Mandatory	400,00H(+10, 00)	13-07-2026		
Airworthiness Directive	Hi-chrome valve guide inspection.		Mandatory	1.000,00H(+3 0,00)		855,50h/ OVD	5.473,50h
Inspection	Engine internal corrosion inspection.		Optional	60m(1m)	5.209,70h/ 26-02-2024	5.97monthOVD	19-03-2026
Service Bulletin	Inspect intake pipe and flange for cracks/fuel staining.		Mandatory	50,00H			
Airworthiness Directive	Inspect fuel injector fuel lines/clamps.		Mandatory	100,00H			
Inspection	Engine overhaul.		Mandatory	2.000,00H(+2 00,00) 144m	19-03-2016	855,50h/ OVD18.03month	5.473,50h/ 19-03-2028
Airworthiness Directive	Inspect engine exhaust valves and guides.		Mandatory	330,00H			
Service Bulletin	Inspect intake/exhaust valves, springs, keys and rockers.		Mandatory	400,00H			
Service Bulletin	Inspect exhaust valve/guide condition for wear or carbon build-up.		Mandatory	300,00H			
Overhaul	Sensenich propeller overhaul.		Mandatory	2.000,00H	6.172,00h/ 12-05-2025	1.843,00h	8.172,00h
Replacement	Replace CO detector.		Mandatory	12m	6.309,00h/ 13-07-2026	9.84month	13-07-2027
Inspection	Clean and Inspect Fuel Selector Filter		Mandatory	100,00H 12m	25-04-2025	105,30h/ OVD4.77monthOVD	6.223,70h/ 25-04-2026
Overhaul	Fuel selector filter replacement.		Mandatory	300,00H(+10, 00) 12cm	6.309,00h/ 13-07-2026	280,00h/ 10.42month	6.609,00h/ 31-07-2027
Replacement	Replace Instrument Air Filter		Mandatory	500,00H(+10, 00) 12m(1mcu mulative)		439,40h	6.768,40h
Replacement	Vacuum relief filter replacement.		Mandatory	100,00H(+10, 00) 12m(1m)	6.309,00h/ 13-07-2026	80,00h	6.409,00h
Inspection	Engine mount inspection at engine removal / 2000H, Socata.		Mandatory	2.000,00H 14 4m	09-06-2015	8.71month	09-06-2027
Retirement	Engine mount retire.		Mandatory	10.000,00H			
Retirement	Nose landing gear mount retire.		Mandatory	10.000,00H		7.874,50h	14.203,50h
Retirement	Wing assy retire.		Mandatory	14.600,00H		8.271,00h	14.600,00h

Aircraft Status



LUFTHAVNSVEJ 34-38
ROSKILDE, 4000
DENMARK

18 September, 2026

Telephone: +45 46191114

Fax:

Tail Number: OY-CDU		Manufacturer: Daher		Model: TB-9		Description: TB-9	
Event	Event Description	ATA	Status	Frequency	Last Compliance	Remaining	Compliance Due
Replacement	Replace ELT battery.		Mandatory	72cm	6.247,60h/ 29-10-2025	61.42month	31-10-2031
Inspection	Annual inspection of ELT.		Mandatory	12m	6.268,40h/ 23-02-2026	5.16month	23-02-2027
Replacement	Replace fire extinguisher.		Mandatory	120m	5.472,60h/ 24-09-2017	12.19month	24-09-2027
Replacement	Replace FAK Niveau 2		Mandatory				
Inspection	Life vest visual inspection.		Mandatory	12cm			
Replacement	Life vest replacement.		Mandatory	120m	01-07-2019	33.45month	01-07-2029
Replacement	Life vest replacement.		Mandatory	120m	01-07-2019	33.45month	01-07-2029
Inspection	Life vest visual inspection.		Mandatory	12cm			
Replacement	Life vest replacement.		Mandatory	120m	01-07-2019	33.45month	01-07-2029
Inspection	Life vest visual inspection.		Mandatory	12cm			
Inspection	Life vest visual inspection.		Mandatory	12cm			
Replacement	Life vest replacement.		Mandatory	120m	01-07-2019	33.45month	01-07-2029
Overhaul	Alternator overhaul, 2000H/144M.		Mandatory	2.000,00H 14 4m	19-05-2021	80.03month	19-05-2033
Overhaul	Carburettor overhaul.		Mandatory	2.000,00H 14 4m	13-07-2026	141.84month	13-07-2038
Replacement	Induction air filter replacement		Mandatory	100,00H(+10, 00) 12m(1m)	5.579,00h/ 13-07-2026	650,00h/ OVD	5.679,00h
Overhaul	Engine fuel pump overhaul.		Mandatory	2.000,00H 14 4cm	21-05-2021	80.42month	31-05-2033
Overhaul	Magneto overhaul.		Mandatory	2.000,00H			
Inspection	Magneto 500 hour inspection.		Mandatory	500,00H(+10, 00)			
Inspection	Magneto 500 hour inspection.		Mandatory	500,00H(+10, 00)			
Overhaul	Magneto overhaul.		Mandatory	2.000,00H			
Replacement	Spark Plug Replacement		Optional	400,00H(+10, 00)	5.579,00h/ 13-07-2026	350,00h/ OVD	5.979,00h
Overhaul	Engine starter overhaul.		Mandatory	2.000,00H 14 4m	4.869,00h/ 19-05-2021	540,00h/ 80.03month	6.869,00h/ 19-05-2033
Inspection	Vacuum pump vane wear inspection.		Mandatory	100,00H(+10, 00) 12m	5.579,00h/ 13-07-2026	650,00h/ OVD9.84month	5.679,00h/ 13-07-2027
Replacement	Vacuum pump replacement, 72M.		Mandatory	72m	09-09-2025	59.71month	09-09-2031
Replacement	Engine mount vibration isolator replacement.		Mandatory	2.000,00H 14 4cm	4.869,00h/ 21-05-2021	540,00h/ 80.42month	6.869,00h/ 31-05-2033
Inspection	Inspect spinner iaw. Duc Helices instructions manual for TB composite spinners.		Mandatory	100,00H(+10, 00) 12m	6.172,00h/ 13-07-2026	57,00h/ OVD9.84month	6.272,00h/ 13-07-2027



LUFTHAVNSVEJ 34-38
ROSKILDE, 4000
DENMARK

18 September, 2026

Telephone: +45 46191114

Fax:

*** End of Document ***