

COMPUTER ORGANIZATION AND DESIGN




The Hardware/Software Interface

Chapter 4

Pipelining Hazards

Pipeline behavior

Pipeline takes new instruction into its IF
 Stage in every clock cycle





Hazards

- Situations that prevent starting the next instruction in the next cycle
 - <u>Dependencies</u>: relationships between instructions that prevent one instruction from being moved past another.
- Structure hazards
 - A required resource is busy
- Data hazard
 - Need to wait for previous instruction to complete its data read/write
- Control hazard
 - Deciding on control action depends on previous instruction



Structure Hazards

A structural hazard occurs when a planned instruction cannot execute in the proper clock cycle because the hardware cannot support the particular combination of instructions that are set to execute in the given clock cycle.

In the laundry analogy, a structural hazard might occur if we used a combo washer/dryer instead of separate washer and dryer machines.



Structure Hazards

- Conflict for use of a resource or inadequate hardware to simultaneously support all instructions in the pipeline in the same clock cycle
- In MIPS pipeline with a single memory
 - Load/store requires data access
 - Instruction fetch would have to stall for that cycle
 - Would cause a pipeline "bubble"
- Hence, pipelined data paths require separate instruction/data memories



PIPELINE HAZARDS

A **structural hazard** occurs when a planned instruction cannot execute in the proper clock cycle because the hardware cannot support the particular combination of instructions that are set to execute in the given clock cycle.

Imagine the following instructions are executed over 8 clock cycles. Notice how in cycle 4, we have a MEM and IF phase executing. If there is only one single memory unit, we will have a structural hazard.

cycle	1	2	3	4	5	6	7	8
lw	IF	ID	EX	MEM	WB			
IW		IF	ID	EX	MEM	WB		
lw			IF	ID	EX	MEM	WB	
lw				IF	ID	EX	MEM	WB



A data hazard occurs when a planned instruction cannot execute in the proper clock cycle because the data that is needed is not yet available.

Consider the following instructions:

add \$s0, \$t0, \$t1

sub \$t2, \$s0, \$t3

cycl e	1	2	3	4	5	6
add	IF	ID	EX	MEM	WB	
			1.5			\

of data access by a previous instruction



The **add** instruction does not write its results to the register file until the fifth stage (cycle 5).

However, the **sub** instruction will need the updated value of **\$s0** in its second stage (cycle 3).

add **\$s0**, \$t0, \$t1

sub \$t2, **\$s0**, \$t3

cycle	1	2	3	4	5	6
add	IF	ID	EX	MEM	WB	
sub		IF	ID	EX	MEM	WB




The worst case solution involves stalling the sub instruction for 3 cycles. While this resolves our dependency issue, it's not ideal. As a note, it is part of the compiler's job to identify dependencies like this and reorder instructions if possible. But we cannot rely on that solution either.

add \$s0, \$t0, \$t1

sub \$t2, \$s0, \$t3

cyc le	1	2	3	4	5	6	7	8	9
add	IF	ID	EX	ME M	WB				
sub®)				IF	ID	EX	ME M	W B


- Optimization: writing to the register to the first half of the clock and reading from the register second half of the clock
 - add \$s0, \$t0, \$t1
 sub \$t2, \$s0, \$t3





Forwarding (aka Bypassing)

- Another solution for the problem is known as **forwarding** (or **bypassing**). This method involves retrieving the data from internal buffers rather than waiting for the data to be updated in the register file or data memory
 - Because the result of the add operation is available at the end of the EX stage, we can grab its value for use in the subsequent instruction.
 - Requires extra connections in the data path





Control Hazards

The third type of hazard, a **control hazard** (or **branch hazard**), occurs when the flow of instruction addresses is not known at the time that the next instruction must be loaded. Let's say we have the following instructions.

beq \$t0, \$t1, L1

sub \$t2, \$s0, \$t3

We have a problem: we do not know what the next instruction should be until the end of the third cycle. But we're automatically fetching the next instruction in the second cycle.

cycle	1	2	3	4	5	6
beq	IF	ID	EX	MEM	WB	
sub		IF	ID	EX	MEM	WB



Control hazards

- Problem: The processor does not know soon enough
 - whether or not a conditional branch should be taken.
 - the target address of a transfer-of-control instruction.
- Solutions:
 - Stall until the necessary information becomes available.
 - Predict the outcome and act accordingly.
- If we stall until the branch target is known, we will always incur a penalty for stalling.
- However, if we predict that the branch is not taken and act accordingly, we will only incur a penalty when the branch actually is taken.

