Когда вы изменили стоимость корневого порта с 4 на 2, повлияло ли это на топологию STP?

Это не повлияло на топологию, так как уменьшалась стоимость оптимального маршрута.

Пример с изменением топологии.

Сначала все маршруты имеют стоимость 4.




Рисунок 1 - схема до изменения

```
This software is provided as is without warranty for internal development and testing purposes only under the terms of the Cisco Early Field Trial agreement. Under no circumstances may this software be used for production purposes or deployed in a production
  environment.
  By using the software, you agree to abide by the terms and conditions of the Cisco Early Field Trial Agreement as well as the terms and conditions of the Cisco End User License Agreement at http://www.cisco.com/go/eula
* Prohibited.
vIOS-L2-01>show span
VLAN0001
  Spanning tree enabled protocol ieee
                   Cost
                                     3 (GigabitEthernet0/2)
                   Port
                   Hello Time 2 sec Max Age 20 sec Forward Delay 15 sec
                                     32769 (priority 32768 sys-id-ext 1)
                  Address
Hello Time
Aging Time
                                     0c26.36cc.0000
                                      2 sec Max Age 20 sec Forward Delay 15 sec
                                    300 sec
Interface
                             Role Sts Cost
                                                          Prio.Nbr Type
Gi0/0
                             Desg FWD 4
                                                          128.2
128.3
128.4
128.5
Gi0/1
Gi0/2
                             Desg FWD 4
                                                                       Shr
                             Root
                                    FWD 4
                                                                       Shr
                             Altn BLK 4
Gi0/3
                                                                       Shr
                             Desg FWD 4
Gi1/1
Gi1/2
                             Desg FWD 4
                             Desg FWD 4
                                                          128.7
                                                                       Shr
   -More--
```

Рисунок 2 - порты 1 коммутатора

Изменим стоимость Gi 0/2 на 1 коммутаторе.




Рисунок 3 - схема после первого изменения

```
0c26.36cc.0000
             Address
                          2 sec Max Age 20 sec Forward Delay 15 sec
15 sec
             Hello Time
Interface
                     Role Sts Cost
                                         Prio.Nbr Type
                     Desg
                          FWD 4
                                                   Shr
                     Altn BLK 44
                                          128.3
128.4
Gi0/2
                                                   Shr
                     Root LRN 4
                                                   Shr
                          FWD 4
                                                   Shr
                     Desg FWD 4
                                          128.7
                                                   Shr
vIOS-L2-01#show spanning-tree
VLAN0001
 Spanning tree enabled protocol ieee
             Cost
                          4 (GigabitEthernet0/3)
             Port
                           2 sec Max Age 20 sec Forward Delay 15 sec
                          0c26.36cc.0000
             Address
             Hello Time
Aging Time
                          2 sec Max Age 20 sec Forward Delay 15 sec 15 sec
Interface
                     Role Sts Cost
                                          Prio.Nbr Type
Gi0/0
                     Desg FWD 4
                          FWD 4
                                                   Shr
                     Altn BLK 44
                                                   Shr
Gi0/3
                     Root FWD 4
                                                   Shr
                     Desg FWD
Gi1/1
Gi1/2
                     Desg
                          FWD 4
                                          128.7
                                                   Shr
  -More--
```

Рисунок 4 - порты 1 коммутатора

Открылся порт Gi 0/3. Маршрут все еще проходит через 1 коммутатор. Изменим стоимость порта Gi 0/3 на 44. Главные изменения в 5 коммутаторе. RP был у Gi 0/0, теперь у Gi 0/2.




Рисунок 5 - схема после второго изменения

```
0c26.36cc.0000
                       Address
                       Hello Time
Aging Time
                                           2 sec Max Age 20 sec Forward Delay 15 sec 15 sec
                                   Role Sts Cost
Interface
                                  Desg FWD 4
Desg FWD 4
Root LIS 44
Altn BLK 44
                                                                    128.1
128.2
128.3
128.4
128.5
Gi0/1
Gi0/2
Gi0/3
Gi1/0
                                   Desg FWD 4
Desg FWD 4
Desg FWD 4
Gi1/1
Gi1/2
                                                                     128.7
                                                                                    Shr
vIOS-L2-01#show spanning-tree
VLAN0001
   Spanning tree enabled protocol ieee Root ID Priority 32769
                                           1 (GigabitEthernet0/0)
                       Hello Time 2 sec Max Age 20 sec Forward Delay 15 sec
                                          32769 (priority 32768 sys-id-ext 1)
0c26.36cc.0000
2 sec Max Age 20 sec Forward Delay 15 sec
15 sec
                      Address
Hello Time
Aging Time
Interface
                                                                    128.1
128.2
128.3
128.4
128.5
                                  ROOT FWD 4
Altn BLK 4
Altn BLK 44
Altn BLK 44
Desg FWD 4
Desg LRN 4
Desg LRN 4
Gi0/1
Gi0/2
Gi1/0
Gi1/1
Gi1/2
                                                                     128.7
                                                                                    Shr
  --More--
```

Рисунок 6 - порты 1 коммутатора