Sleep Timeout

Sleep Timeout = Disable	Sleep Timeout = 1sec
51000	51001
Sleep Timeout = 2sec	Sleep Timeout = 3sec
51002	51003
Sleep Timeout = 4sec	Sleep Timeout = 5sec
51004	51005
Sleep Timeout = 10sec	Sleep Timeout = 20sec
5100A	51014
Sleep Timeout = 30sec	Sleep Timeout = 1min
5101E	5103C
Sleep Timeout = 2min	Sleep Timeout = 5min
51078	5112C
Sleep Timeout = 10min	
51258	