Barcode Options

Codabar - do NOT transmit start/stop	Codabar - transmit start/stop
300000001	310000001
Convert UPCE to UPCA	Do NOT convert UPCE to UPCA
300000200	3100000200
Convert EAN8 to EAN13	Do NOT convert EAN8 to EAN13
300000400	3100000400
Convert UPCE to EAN13	Do NOT convert UPCE to EAN13
300000800	3100000800
Return Check Digit	Do NOT Return Check Digit
3000001000	3100001000
Verify Check Digit	Do NOT Verify Check Digit
3000002000	3100002000
Convert UPCA to EAN13	Do NOT Convert UPCA to EAN13
3000080000	3100080000

Do NOT verify check digit for I2of5
3100400000
Do NOT verify check digit for Code39
3100800000
Do NOT return check digit for I2of5
3104000000
Do NOT return check digit for Code39
3108000000
Do NOT return check digit for UPCE
3110000000
Do NOT return check digit for UPCA
3120000000
Do NOT return check digit for EAN8
3140000000

Return check digit for EAN13



3080000000

Do NOT return check digit for EAN13



3180000000